



**DX59HKE**


report date: 2024-03-28

General information

Make	NISSAN
Model	PATHFINDER
Colour	Grey
Year of manufacture	2009
Gearbox	-

Engine & fuel consumption

Engine capacity	2.488 cc
Fuel type	Diesel
CO2 emission	264 g/km
CO2 label	M





Internet history

Entry 2

Date	2022-07-01
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

Entry 1

Date	2022-06-23
Pictures	20
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2023-08-17
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	29
Total items failed	3

MOT #16	2022-08-18 14:33
MOT test number	816523390629
Result	✓ Passed
Next expiry date	2023-08-17
Advice	Front Prop shaft joint worn, but not excessively prop Rear U.J (6.1.7 (c) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated inner clip missing (6.1.7 (g) (i))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Rear Exhaust has a minor leak of exhaust gases box (6.1.2 (a))

**MOT #15**

2022-08-04 11:43

**MOT test number**

832107920800

**Result**

✗ Failed

**Advice** Front Prop shaft joint worn, but not excessively prop Rear U.J (6.1.7 (c) (i))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated inner clip missing (6.1.7 (g) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases box (6.1.2 (a))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #14**

2021-11-08 09:35

**MOT test number**

420957229345

**Result**

✓ Passed

**Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))**MOT #13**

2020-11-24 12:02

**MOT test number**

947223600140

**Result**

✓ Passed

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** 3rd row seat belts not checked, boot full

**MOT #12** 2020-11-24 12:02**MOT test number** 935273082513**Result** ✗ Failed**Advice** 3rd row seat belts not checked, boot full**Pass with rectification** Battery insecure and likely to fall from carrier (4.13 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11** 2020-06-16 14:16**MOT test number** 105139312942**Result** ✓ Passed**MOT #10** 2019-08-02 12:52**MOT test number** 122383760321**Result** ✓ Passed**MOT #9** 2019-08-02 12:52**MOT test number** 492125500444**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #8** 2018-08-07 15:26**MOT test number** 533240871092**Result** ✓ Passed**MOT #7** 2017-08-08 09:35**MOT test number** 575673842140**Result** ✓ Passed

**MOT #6** 2016-08-15 11:06**MOT test number** 250882931590**Result** ✓ Passed**MOT #5** 2015-09-07 10:12**MOT test number** 538265292857**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Lower Front suspension has slight movement at a suspension ball joint (2.5.A.1c)
- Advice** Nearside Front Lower Front suspension has slight movement at a suspension ball joint (2.5.A.1c)

**MOT #4** 2014-09-10 09:45**MOT test number** 828603654200**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2013-09-12 09:34**MOT test number** 138675053288**Result** ✓ Passed

- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #2** 2013-01-11 16:34**MOT test number** 126491613032**Result** ✓ Passed

- Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)



MOT #1	2013-01-11 10:45
MOT test number	777671313079
Result	✗ Failed
Fail	Service brake: efficiency below requirements (3.7.C.1a)
Advice	Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
Advice	Service brake juddering slightly (3.7.C.2)
Advice	Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)



Tax & MOT check

✖  
Untaxed

Tax expired:  
1 January 2023

✖  
MOT

Expired:  
17 August 2023

Tax status	Expired at 1 January 2023
Days left	483 days too late
MOT expiry date	17 August 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	<b>DX59HKE</b>
Plate since	2019-03-28
Current registration	<b>DX59HKE</b>
Plate since	2019-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-10-07
Last registration	2022-08-18
Complete history	<a href="#">See info</a>



Registration #1	2009-10-07	9 mi
Registration #2	2013-01-11	20.877 mi
Registration #3	2013-01-11	20.877 mi
Registration #4	2013-09-12	23.892 mi
Registration #5	2014-09-10	42.303 mi
Registration #6	2015-09-07	58.285 mi
Registration #7	2016-08-15	70.654 mi
Registration #8	2017-08-08	84.695 mi
Registration #9	2018-08-07	100.382 mi
Registration #10	2019-08-02	114.847 mi
Registration #11	2020-08-02	131.277 mi
Registration #12	2021-08-02	151.277 mi
Registration #13	2022-08-02	171.277 mi
Registration #14	2023-08-02	191.277 mi
Registration #15	2024-08-02	211.277 mi
Registration #16	2025-08-02	231.277 mi
Registration #17	2026-08-02	251.277 mi
Registration #18	2027-08-02	271.277 mi
Registration #19	2028-08-02	291.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★☆

Video

[see crash video](#)



Additional information

Number of seats	7
Engine number	NOT KNOWN