



report date: 2024-03-28

General information

Make	CITROEN
Model	NEMO 590 ENTERPRISE HDI
Colour	White
Year of manufacture	2015
Top speed	97 mph
0 - 60 mph	16.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D





Internet history

Entry 2


Date	2023-03-31
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-03-19
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-13
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	14
Total items failed	0

MOT #9	2024-04-09 13:13
MOT test number	171747008436
Result	✓ Passed
Next expiry date	2025-04-13

MOT #8	2024-04-04 13:07
MOT test number	316021110564
Result	✗ Failed
MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #7	2023-04-14 06:23
MOT test number	829126539285
Result	✓ Passed

MOT #6	2023-04-11 13:13
MOT test number	398092978988
Result	✗ Failed
Advice Nearside Play in steering rack inner joint(s)	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))	

**MOT #5** 2022-12-02 09:49**MOT test number** 376434207538**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Shock absorbers has a slightly worn bush top bush (5.3.2 (c))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Shock absorbers has a slightly worn bush top bush (5.3.2 (c))**MOT #4** 2021-12-03 14:11**MOT test number** 522329678541**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2020-12-08 11:44**MOT test number** 275459894333**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2019-11-23 10:02**MOT test number** 201174286568**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2018-12-10 15:42**MOT test number** 913670129985**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
13 April 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	13 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-10
Last registration	2024-04-09
Complete history	See info



Registration #1	2015-09-10	27 mi
Registration #2	2018-12-10	35.670 mi
Registration #3	2019-11-23	49.159 mi
Registration #4	2020-12-08	55.685 mi
Registration #5	2021-12-03	65.247 mi
Registration #6	2022-05-20	75.277 mi
Registration #7	2022-05-20	75.277 mi
Registration #8	2022-05-20	75.277 mi
Registration #9	2022-05-20	75.277 mi
Registration #10	2022-05-20	75.277 mi
Registration #11	2022-05-20	75.277 mi
Registration #12	2022-05-20	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	74%
Pedestrian	55%
Safety systems	29%
Overall rating	58%
Video	see crash video



Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	00015838972