





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI BLUEMOTION TECHNOLOGY
Colour	Silver
Year of manufacture	2018
Top speed	123 mph
0 - 100 km/h	10.2 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	85 kW / 116 HP / 113 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-01

Pictures 26

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



749445670248

MOT history

MOT test number

MOT expiry date	2024-10-18
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #5	2023-10-18 16:17
MOT test number	539895096794
Result	✓ Passed
Next expiry date	2024-10-18

MOT #4	2022-10-17 11:04
MOT test number	140617271506
Result	✓ Passed

MOT #3	2021-10-19 12:25
MOT test number	851330169929
Result	✓ Passed

MOT #2	2021-03-31 11:28

Result		✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing and offside rear (5.2.3 (d) (ii))	
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice (5.3.2 (b))	Nearside Front Shock absorbers light misting of oil or has limited damping effect and offs	ide front
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge and offside rear (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2021-03-27 11:46

MOT test number 422919707661

Result

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge and offside rear (5.2.3 (e))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing and offside rear (5.2.3 (d) (ii))

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect and offside front

(5.3.2 (b))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	18 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11




report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra VOLKSWAGEN salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-28
Last registration	2023-10-18
Complete history	See info



Registration #1	2018-03-28	8 mi
Registration #2	2021-03-27	48.208 mi
Registration #3	2021-03-31	48.208 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		11,177 mi

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	89%
Pedestrian	65%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2027 mm
Height	1492 mm
Length	4258 mm
Wheel base	2620 mm
Kerb weight	1223 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2

CarCheck.co.uk page 11/11

Engine number

DDYA635499