



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 PURETECH FLAIR
Colour	White
Year of manufacture	2015
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	107 g/km
CO2 label	B








Internet history

Entry 1

Date	2021-08-01
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-16
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	21
Total items failed	21

MOT #13	2024-04-17 14:01
MOT test number	317868728314
Result	✓ Passed
Next expiry date	2025-04-16
Advice	Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #12	2024-04-17 08:01
MOT test number	242148692275
Result	✗ Failed
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Fail	Nearside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))



MOT #11	2023-03-17 10:40
MOT test number	791393682819
Result	✓ Passed

MOT #10	2023-02-17 12:59
MOT test number	731143101333
Result	✗ Failed
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #9	2021-12-23 10:05
MOT test number	160169243426
Result	✓ Passed

MOT #8	2021-12-23 10:05
MOT test number	610369625518
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #7** 2020-12-21 17:39**MOT test number** 646694600957**Result** ✓ Passed**MOT #6** 2020-12-19 14:24**MOT test number** 627878836762**Result** ✗ Failed

- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
- Fail** Exhaust silencer insecure (8.1.1 (b) (i))

MOT #5 2020-02-06 13:31**MOT test number** 376376754134**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #4 2020-02-06 11:10**MOT test number** 827434145480**Result** ✗ Failed

- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Exhaust system insecure (6.1.2 (a))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #3** 2019-02-21 14:54**MOT test number** 439364232558**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.9mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3.5mm (5.2.3 (e))**Advice** Central Exhaust mounting defective (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 1.8mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3.2mm (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Nail in tyre**MOT #2** 2018-02-26 16:41**MOT test number** 360294477460**Result** ✓ Passed**Advice** Rear exhaust bracket insecure**MOT #1** 2018-02-26 16:04**MOT test number** 404292853715**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Rear exhaust bracket insecure



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
16 April 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	YK15CKO
Plate since	2015-03-29
Current registration	YK15CKO
Plate since	2015-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2015-03-01
Last registration	2024-04-17
Complete history	See info



Registration #1	2015-03-01	29 mi
Registration #2	2018-02-26	27.438 mi
Registration #3	2018-02-26	27.438 mi
Registration #4	2019-02-21	39.945 mi
Registration #5	2020-02-06	52.460 mi
Registration #6	2020-02-06	52.464 mi
Registration #7	2020-12-19	60.540 mi
Registration #8	2020-12-21	60.540 mi
Registration #9	2020-12-21	60.540 mi
Registration #10	2020-12-21	60.540 mi
Registration #11	2020-12-21	60.540 mi
Registration #12	2020-12-21	60.540 mi
Registration #13	2020-12-21	60.540 mi
Registration #14	2020-12-21	60.540 mi
Registration #15	2020-12-21	60.540 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	965 kg
Max. allowed weight	1500 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B2150067940