





General information

Make	ΤΟΥΟΤΑ
Model	COROLLA T180 D-CAT
Colour	Grey
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	164 g/km
CO2 label	G







Internet history

Entry	1
Date	

Pictures

2021-10-06

22

Listing price

View report









source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-21
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	14
Total items failed	7

MOT #16	2023-09-08 14:37
MOT test number	506554203624
Result	✓ Passed
Next expiry date	2024-09-21
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #152022-09-13 16:38MOT test number198897329662ResultPassedAdviceRear Brake pad(s) wearing thin (1.1.13 (a) (ii))AdviceFront Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14	2021-09-22 11:58
MOT test number	208757739981
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #13	2020-12-31 09:32
MOT test number	691910335555
Result	✓ Passed
MOT #12	2020-12-31 09:32
MOT test number	914750908915
Result	× Failed
Pass with rectification (ii))	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification	Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #11	2019-07-31 16:10
MOT test number	932179732908
Result	✓ Passed
Advice Under tray fitted.	
Advice Nearside Front Non of	igatory mirror damaged

MOT #10	2019-07-30 16:13
MOT test number	647356035551
Result	🗙 Failed
Advice Nearside Front Non obligatory mirror damaged Fail (ii)) Front Lower Suspension arm ball joint dust cover no longer prevents the in Advice Under tray fitted.	gress of dirt both (5.3.4 (b)





MOT #9	2018-06-19 17:09
MOT test number Result	441706471408
Advice Nearside Front L	ower Bumper mountings corroded but not likely to become detached (6.1.4 (a) (i))
Advice Offside Rear Chi	Id Seat fitted not allowing full inspection of adult belt
Minor Offside Rear Tyre	e obviously under inflated (5.2.3 (h) (i))
Advice Nearside Front S	Shock absorbers has slight external damage to the casing slight play (5.3.2 (b))
MOT #8	2017-06-10 10:06
MOT test number	943875370912
Result	✓ Passed
MOT #7	2016-09-08 14:07
MOT test number	823983319015
Result	✓ Passed
MOT #6	2015-09-10 14:47
MOT test number	469657744697
Result	✓ Passed
MOT #5	2014-09-09 12:23
MOT test number	467692854261
Result	✓ Passed
MOT #4	2014-09-09 12:23
MOT test number	649722154242
Result	× Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Pass with rectification	Offside Headlamp aim too low (1.8)





MOT #3	2013-08-27 11:31
MOT test number	237729633215
Result	✓ Passed
MOT #2	2012-09-05 13:13
MOT test number	167969442208
Result	✓ Passed
MOT #1	2011-09-05 11:53
MOT test number	558558941248
Result	Passed



Tax & MOT check

✓ Taxed	√ МОТ
Tax due: 1 October 2024	Expires: 21 September 2024
Tax status	Valid until 1 October
Days left	155
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K
Damage 2	AMPL
Date	NE
Category	AMP
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6 10.200
Auction value	4 10.000
Average private trade value	4 11 200





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plate	5.
Number of plates	7
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-19
Last registration	2023-09-08
Complete history	See info



Registration #1	2008-09-19	9 mi
Registration #2	2011-09-05	4.744 mi
Registration #3	2012-09-05	5.707 mi
Registration #4	2013-08-27	6.738 mi
Registration #5	2014-09-09	7.924 mi
Registration #6	2015-09-10	10.333 mi
Registration #7	2016-09-08	11.925 mi
Registration #8	2017-06-10	12.863 mi
Registration #9	2018-06-19	22.618 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1760 mm
Height	1515 mm
Length	4220 mm
Wheel base	2600 mm
Kerb weight	1470 kg
Max. allowed weight	1920 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	4405305329