



report date: 2024-03-28

General information

Make	SUZUKI
Model	GRAND VITARA SZ5
Colour	Black
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	167 BHP
Max. torque	227 Nm at 3.800 rpm
Engine capacity	2.393 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	37.2 mpg
Consumption combined	31.4 mpg
CO2 emission	208 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-06-11
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-02-02
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	25
Total items failed	5

MOT #14	2023-02-03 16:53
MOT test number	601351751164
Result	✓ Passed
Next expiry date	2024-02-02
Advice	General condition of vehicle under body and various components corrosive
Advice	Nearside side repeater poor
Advice	Front Differential bushes worn

MOT #13	2022-01-19 16:48
MOT test number	832219827307
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear brake pads wearing low
Advice	Rear Differential oil seal leaking N/S?
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	General condition of vehicle under body and components corrosive
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Central under body Fuel lines have corrosion

**MOT #12** 2021-01-05 09:35**MOT test number** 555194783595**Result** ✓ Passed

Advice Rear Brake pipe corroded, covered in grease or other material pipes covered in grease (1.1.11 (c))

MOT #11 2020-01-06 11:53**MOT test number** 623843033477**Result** ✓ Passed

- Advice** Heat shield missing no risk of fire
- Advice** Oil leak, but not excessive transfare box forward output seal (8.4.1 (a) (i))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Wipers smearing slightly
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10 2019-01-18 09:55**MOT test number** 473477314822**Result** ✓ Passed

- Advice** Fuel pipe corroding at rear
- Advice** Front Items removed from driver's view prior to test Camera

MOT #9 2018-01-05 11:56**MOT test number** 797982701336**Result** ✓ Passed**MOT #8** 2017-01-20 09:23**MOT test number** 505143445593**Result** ✓ Passed

**MOT #7** 2017-01-19 17:00**MOT test number** 227511262897**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid both (8.2.3)**Fail** Offside Side repeater not working (1.4.A.2c)**MOT #6** 2016-02-10 09:41**MOT test number** 246124747454**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-02-24 12:20**MOT test number** 619485455038**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-02-24 11:00**MOT test number** 115085055402**Result** ✗ Failed**Fail** Offside Windscreen wiper blade insecure (8.2.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)



MOT #3	2014-02-28 10:48
MOT test number	766949954054
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2013-03-04 10:06
MOT test number	256523863064
Result	✓ Passed

MOT #1	2013-03-04 10:06
MOT test number	547563663045
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (1.8)
Pass with rectification	Nearside Headlamp aim too low (1.8)



Tax & MOT check

X

Untaxed

Tax expired:
27 February 2024

X

MOT

Expired:
2 February 2024

Tax status	Expired at 27 February 2024
Days left	61 days too late
MOT expiry date	2 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	YG10CMK
Plate since	2019-03-28
Current registration	YG10CMK
Plate since	2019-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	15
First mileage registration	2010-03-05
Last registration	2023-02-03
Complete history	See info



Registration #1	2010-03-05	22 mi
Registration #2	2013-03-04	19.201 mi
Registration #3	2014-02-28	25.561 mi
Registration #4	2015-02-24	32.158 mi
Registration #5	2015-02-24	32.158 mi
Registration #6	2016-02-10	38.994 mi
Registration #7	2017-01-19	43.990 mi
Registration #8	2017-01-20	43.990 mi
Registration #9	2019-05-20	55.377 mi
Registration #10	2019-05-20	55.377 mi
Registration #11	2019-05-20	55.377 mi
Registration #12	2019-05-20	55.377 mi
Registration #13	2019-05-20	55.377 mi
Registration #14	2019-05-20	55.377 mi
Registration #15	2019-05-20	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1695 mm
Length	4575 mm
Wheel base	2640 mm
Kerb weight	1552 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	J24B-1016955