



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE SCENIC EXPRESSION + 16V SCENIC
Colour	Silver
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg





Internet history

Entry 1

Date	2021-08-28
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history****MOT #21** 2021-01-27 09:58**MOT test number** 683930449224**Result** ✓ Passed**Next expiry date** 2022-01-26**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement axle (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement axle (5.3.4 (a) (i))**MOT #20** 2019-08-07 11:56**MOT test number** 594435018951**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear axle bushes perished**MOT #19** 2019-08-07 10:08**MOT test number** 842347213046**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear axle bushes perished**Fail** Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

**MOT #18**

2018-08-16 14:04

**MOT test number**

947952028631

**Result**

✓ Passed

**Advice**

Front Brake disc worn, pitted or scored, but not seriously weakened Both front brake discs corroded on there inner brake faces (1.1.14 (a) (ii))

**MOT #17**

2018-08-15 09:28

**MOT test number**

291396430625

**Result**

✗ Failed

**Fail**

Nearside Front Position lamp not working (4.2.1 (a))

**Fail**

Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**Advice**

Front Brake disc worn, pitted or scored, but not seriously weakened Both front brake discs corroded on there inner brake faces (1.1.14 (a) (ii))

**Fail**

Brake fluid contaminated Dirty (1.8 (a))

**Fail**

Offside Front Position lamp not working (4.2.1 (a))

**Fail**

Rear Stop lamp(s) all not working (4.3.1 (a) (iii))

**Fail**

Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #16**

2017-08-07 12:06

**MOT test number**

114713117987

**Result**

✓ Passed

**Advice**

Rear Direction indicators slightly discoloured both rears (1.4.A.2f)

**MOT #15**

2016-08-10 12:06

**MOT test number**

136984506752

**Result**

✓ Passed

**Advice**

Offside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice**

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #14** 2015-08-12 12:24**MOT test number** 348374125403**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #13** 2014-08-12 11:24**MOT test number** 929184124204**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #12** 2014-08-11 12:34**MOT test number** 339623024437**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #11** 2013-08-13 15:40**MOT test number** 117825523244**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2013-08-12 11:56**MOT test number** 129854023268**Result** ✗ Failed

- Fail** Hazard warning switch faulty (1.4.B.1d)
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2012-07-31 08:56**MOT test number** 366383512236**Result** ✓ Passed

- Notice** Both rear tyre sidewalls starting to perish

**MOT #8** 2012-07-31 08:56**MOT test number** 509453212274**Result** ✗ Failed

- Pass with rectification** Offside Rear Direction indicators incorrect colour (1.4.A.2f)
- Pass with rectification** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)
- Notice** Both rear tyre sidewalls starting to perish

**MOT #7** 2011-08-12 10:32**MOT test number** 109234921281**Result** ✓ Passed**MOT #6** 2010-08-09 14:54**MOT test number** 442461920273**Result** ✓ Passed

**MOT #5** 2009-08-14 15:17**MOT test number** 804036629280**Result** ✓ Passed**MOT #4** 2008-08-09 09:24**MOT test number** 141422228211**Result** ✓ Passed**Notice** Both front tyres wearing on outer edges**MOT #3** 2007-08-11 10:25**MOT test number** 280313927205**Result** ✓ Passed**Notice** Front brake pads wearing thin**Notice** Rear brake pads wearing thin**MOT #2** 2006-08-12 09:22**MOT test number** 410424826214**Result** ✓ Passed**MOT #1** 2005-05-23 12:23**MOT test number** 294043545455**Result** ✓ Passed**Notice** Nearside rear tyre wall cut(not down to cord)also has a nail in it!**Notice** Offside rear light lense damaged,water inside lense!**Notice** Tyre in spare has a bulge,inner wall**Notice** Both rear indicators starting to show white light



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-07-15
Last registration	2021-01-27
Complete history	<a href="#">See info</a>



Registration #1	2002-07-15	21 mi
Registration #2	2005-05-23	11.903 mi
Registration #3	2006-08-12	21.537 mi
Registration #4	2007-08-11	31.474 mi
Registration #5	2008-08-09	42.214 mi
Registration #6	2009-08-14	50.039 mi
Registration #7	2010-08-09	54.549 mi
Registration #8	2011-08-12	57.196 mi
Registration #9	2012-07-31	59.415 mi
Registration #10	2013-08-12	61.471 mi
Registration #11	2013-08-13	61.483 mi
Registration #12	2013-08-13	61.483 mi
Registration #13	2013-08-13	61.483 mi
Registration #14	2013-08-13	61.483 mi
Registration #15	2013-08-13	61.483 mi
Registration #16	2013-08-13	61.483 mi
Registration #17	2013-08-13	61.483 mi
Registration #18	2013-08-13	61.483 mi
Registration #19	2013-08-13	61.483 mi
Registration #20	2013-08-13	61.483 mi
Registration #21	2013-08-13	61.483 mi
Registration #22	2013-08-13	61.483 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating 

★★★★★

Video [see crash video](#)

Dimensions & weight

Width	2007 mm
Height	1600 mm
Length	4140 mm
Wheel base	2580 mm
Kerb weight	1250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	D672680