



M28GKR

report date: 2024-03-29

General information

Make	MINI
Model	MINI COOPER D
Colour	Black
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-06-12
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-24
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	19
Total items failed	7

MOT #14	2023-09-12 13:46
MOT test number	626802798547
Result	✓ Passed
Next expiry date	2024-09-24

MOT #13	2022-09-22 14:14
MOT test number	573057995916
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

MOT #12	2021-09-24 09:44
MOT test number	638765812271
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2020-09-25 10:22**MOT test number** 332547624662**Result** ✓ Passed**MOT #10** 2019-05-04 09:39**MOT test number** 361385286956**Result** ✓ Passed**Advice** Under covers fitted unable to fully test some items**MOT #9** 2018-05-05 09:20**MOT test number** 895442829681**Result** ✓ Passed**Advice** Under trays fitted unable to fully test some items**MOT #8** 2017-05-08 15:54**MOT test number** 427032121657**Result** ✓ Passed**MOT #7** 2017-05-06 11:52**MOT test number** 472336381803**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)

**MOT #6** 2016-05-06 10:38**MOT test number** 866547064987**Result** ✓ Passed**MOT #5** 2015-05-06 16:12**MOT test number** 759206625145**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2015-05-06 15:27**MOT test number** 787866825159**Result** ✗ Failed**Fail** Nearside Rear rear brake excessively fluctuating (3.7.B.3)**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Offside Rear rear brake excessively fluctuating (3.7.B.3)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2014-05-07 14:29**MOT test number** 157987624199**Result** ✓ Passed**MOT #2** 2013-11-20 12:39**MOT test number** 857034123311**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #1	2013-11-20 12:39
MOT test number	457174423465
Result	✗ Failed
Pass with rectification	Rear Windscreen washer provides insufficient washer liquid (8.2.3)
Notice	Under-trays fitted obscuring some underside components
Pass with rectification	Rear registration plate delaminated (6.3.1d)
Notice	Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
24 September 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	24 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-12-08
Last registration	2023-09-12
Complete history	See info



Registration #1	2010-12-08	11 mi
Registration #2	2013-11-20	21.370 mi
Registration #3	2014-05-07	23.223 mi
Registration #4	2015-05-06	25.065 mi
Registration #5	2015-05-06	25.065 mi
Registration #6	2016-05-06	26.768 mi
Registration #7	2017-05-06	27.846 mi
Registration #8	2017-05-08	27.846 mi
Registration #9	2019-05-08	28.277 mi
Registration #10	2019-05-08	28.277 mi
Registration #11	2019-05-08	28.277 mi
Registration #12	2019-05-08	28.277 mi
Registration #13	2019-05-08	28.277 mi
Registration #14	2019-05-08	28.277 mi
Registration #15	2019-05-08	28.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	70667572