



report date: 2024-03-29

General information

Make	MINI
Model	COOPER D
Colour	Blue
Year of manufacture	2012
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-07-12
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	21
Total items failed	6

## MOT #13 2023-07-03 14:00

MOT test number 637489732980

Result ✓ Passed

Next expiry date 2024-07-12

**Advice** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

## MOT #12 2022-07-13 10:03

MOT test number 818827612010

Result ✓ Passed

## MOT #11 2022-07-13 10:03

MOT test number 608422945233

Result ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #10** 2021-10-15 08:22**MOT test number** 406316526791**Result** ✓ Passed**Minor** Front Position lamp incorrect colour (4.2.3 (a) (i))**MOT #9** 2021-10-15 08:22**MOT test number** 529818006793**Result** ✗ Failed**Minor** Front Position lamp incorrect colour (4.2.3 (a) (i))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**MOT #8** 2020-10-14 08:16**MOT test number** 987989554419**Result** ✓ Passed**MOT #7** 2020-10-14 08:16**MOT test number** 975169006650**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Offside Front Headlamp aim too low and too far to the right. (4.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #6** 2019-10-17 15:02**MOT test number** 253659892803**Result** ✓ Passed**MOT #5** 2018-10-31 09:35**MOT test number** 782899729940**Result** ✓ Passed

**MOT #4** 2017-10-31 11:39**MOT test number** 973982888749**Result** ✓ Passed**Advice** Hi-level brake lamp not working**MOT #3** 2016-11-04 12:55**MOT test number** 757868955424**Result** ✓ Passed**MOT #2** 2015-10-06 11:53**MOT test number** 888394988504**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Engine covers fitted obscuring some components in the engine bay.**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Under trays fitted obscuring some underside components.**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1

2015-10-06 11:53

MOT test number

441960156800

Result

✖ Failed

- Advice

Rear Brake pad(s) wearing thin (3.5.1g)
- Pass with rectification

Offside Front Headlamp aim too low and too far to the right. (1.8)
- Advice

Engine covers fitted obscuring some components in the engine bay.
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Under trays fitted obscuring some underside components.
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
12 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	12 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>ST62DFK</b>
Plate since	2019-09-29
Current registration	<b>ST62DFK</b>
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-10-18
Last registration	2023-07-03
Complete history	<a href="#">See info</a>



Registration #1	2012-10-18	23 mi
Registration #2	2015-10-06	39.688 mi
Registration #3	2015-10-06	39.688 mi
Registration #4	2016-11-04	47.582 mi
Registration #5	2017-10-31	56.448 mi
Registration #6	2018-10-31	63.838 mi
Registration #7	2019-10-17	73.092 mi
Registration #8	2020-10-14	80.192 mi
Registration #9	2020-10-14	80.192 mi
Registration #10	2020-10-14	80.192 mi
Registration #11	2020-10-14	80.192 mi
Registration #12	2020-10-14	80.192 mi
Registration #13	2020-10-14	80.192 mi
Registration #14	2020-10-14	80.192 mi
Registration #15	2020-10-14	80.192 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	70817962