






General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE
Colour	Blue
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	А







Internet history

Entry	2

Date Pictures 2021-09-11

12

Listing price

View report



source: cargurus.co.uk

Entry 1

Date	2021-09-10
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-25
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	13
Total items failed	7

МОТ #9	2023-07-26 09:18
MOT test number	225933283694
Result	✓ Passed
Next expiry date	2024-07-25

MOT #8	8	2023-07-26 07:49
MOT te	est number	152023732890
Result		🗙 Failed
Fail	Offside Position lamp not working (4.2.1 (a) (ii))	
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
Fail	Rear Exhaust system insecure (6.1.2 (a))	

MOT #7		2022-09-07 13:20
MOT test	number	755532645338
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #6	2022-09-05 14:57	
MOT test number	885924958286	
Result	🗙 Failed	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))		
Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))		
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	

MOT #5	2021-09-08 15:12
MOT test number	301975069219
Result	✓ Passed

MOT #4		2021-01-22 12:16
MOT test	number	652391180663
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3	2020-01-07 15:51
MOT test number	122270039316
Result	✓ Passed





MOT #2		2019-01-05 10:00
MOT test	number	526462214181
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Undertrays + sill covers fitted	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin borderline pass (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear discs lipped	

MOT #1	2018-01-04 10:43
MOT test number	613136715263
Result	✓ Passed
Advice Front Inner Brake pad(s) wearing thin Both sides (3.5.1g)	



Tax & MOT check

✓ Taxed Tax due: 1 November 2024	✓ MOT Expires: 25 July 2024
Tax status	Valid until 1 November
Days left	185
MOT expiry date	25 July 2024
Full MOT history	See MOT history
Tax calculation	
Vehicle class	49

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	VAMPL
Date	
Category	AMP
Туре	

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-01-05
Last registration	2023-07-26
Complete history	<u>See info</u>



Registration #1	2015-01-05	19 mi
Registration #2	2018-01-04	22.814 mi
Registration #3	2019-01-05	33.518 mi
Registration #4	2020-01-07	45.367 mi
Registration #5	2021-01-22	55.470 mi
Registration #6	2021-09-08	59.387 mi
Registration #7		11.777 mi
Registration #7 Registration #8		10.000 est
-		01.000 est 01.000 est 01.000 est
Registration #8		01,000 est 01,000 est 01,000 est 01,000 est
Registration #8 Registration #9		01,000 440 01,000 440 01,000 440 01,000 440 01,000 440





Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight	
Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg
Additional information	
Additional information Fuel tank capacity	48 I
	48 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 3