





report date: 2024-03-29

General information

Make	CITROEN
Model	DISPATCH HDI 900 P/V
Colour	Silver
Year of manufacture	2004
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/18



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-20

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/18



report date: 2024-03-29

MOT history

MOT expiry date	2024-07-03
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	66
Total items failed	20

MOT #25		2023-07-04 15:48
MOT test	number	253159002520
Result		✓ Passed
Next exp	iry date	2024-07-03
Advice	Nearside Side repeater slightly discoloured (4.4.3 (a))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Offside Side repeater slightly discoloured (4.4.3 (a))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice	Power steering pipe/hose has slight seepage (2.1.5 (a))	
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources	s (4.7.1 (b) (i))

CarCheck.co.uk page 3/18



Fail

Fail

Horn not working (7.7 (a))

HD54VDP

report date: 2024-03-29

MOT #24 2023-06-30 11:25

MOT test number 885875973163

Result **X** Failed **Advice** Nearside Side repeater slightly discoloured (4.4.3 (a)) **Advice** Power steering pipe/hose has slight seepage (2.1.5 (a)) **Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) Fail **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Brake pedal anti-slip provision missing (1.1.2 (c)) Oil leak, but not excessive (8.4.1 (a) (i)) **Advice Advice** Offside Side repeater slightly discoloured (4.4.3 (a)) Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/18



report date: 2024-03-29

MOT #23 2022-06-22 15:55

MOT test number 585110774099

Result Passed

Advice Power steering component has slight seepage from a component (2.1.5 (a))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #22 2022-06-20 10:18

MOT test number 136934216487

Result X Failed

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Central Upper Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Emissions not tested (8.2.2.2 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Horn not working (7.7 (a))

Fail Front Exhaust has a major leak of exhaust gases broken off (6.1.2 (a))

Advice Power steering component has slight seepage from a component (2.1.5 (a))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 5/18



MOT #21

HD54VDP

report date: 2024-03-29

2021-06-22 14:19

MOT test number

286341822394

Result

✓ Passed

Advice Rear axle has surface corrosion

Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Front subframe has surface corrosion

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #20 2019-03-26 16:31

MOT test number 626619935805

Result ✓ Passed

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Exhaust cat rattle

MOT #19 2019-03-26 10:01

MOT test number 727243492251

Result × Failed

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure Inner side wall (5.2.3 (d) (ii))

Advice Exhaust cat rattle

Fail Nearside Front Position lamp not working (4.2.1 (a))

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 6/18



report date: 2024-03-29

MOT #18 2018-04-04 08:30 359511247360 **MOT** test number ✓ Passed Result **Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Tie bar/rod corroded but not seriously weakened Across rear axle (2.4.G.1)

Advice

Advice

Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

MOT #17 2017-03-21 10:49

MOT test number 311330432024

Result ✓ Passed

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt Required soon (2.5.C.1a)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Inner edges of tyres wearing

CarCheck.co.uk page 7/18



report date: 2024-03-29

MOT #16 2017-03-21 10:49

MOT test number 759590633430

Result X Failed

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt

Required soon (2.5.C.1a)

Advice Front Inner edges of tyres wearing

Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Advice Offside Rear coil spring corroded (2.4.C.1b)

Pass with rectification Exhaust system not adequately supported Centre and rear (7.1.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #15 2016-04-08 15:55

MOT test number 277732214887

Result \rightarrow Passed

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #14 2016-04-08 12:44

MOT test number 322236745477

Result X Failed

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

MOT #13 2015-09-04 10:39

MOT test number 219472226667

Result ✓ Passed

CarCheck.co.uk page 8/18



report date: 2024-03-29

MOT #12 2015-09-04 10:39

MOT test number 773396226159

Result X Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #11 2014-09-05 13:56

MOT test number 559908644228

Result Passed

Advice Brake pipe slightly corroded (3.6.B.2c)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #10 2014-09-05 12:23

MOT test number 385038644267

Result X Failed

Fail Offside Side repeater incorrect colour (1.4.A.2f)

Advice Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice Brake pipe slightly corroded (3.6.B.2c)

Fail Nearside Side repeater incorrect colour (1.4.A.2f)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Offside Front Direction indicator slightly discoloured (1.4.A.2f)

MOT #9 2013-08-30 09:39

MOT test number 565292643286

Result \(\sqrt{Passed} \)

MOT #8 2012-09-05 17:01

MOT test number 705689142233

Result ✓ Passed

CarCheck.co.uk page 9/18



report date: 2024-03-29

MOT test number

867469442215

Result

Fail Nearside Front front brake juddering severely (3.7.A.2b)

Notice Advise high level brake light inop

Fail Offside Front front brake juddering severely (3.7.A.2b)

 MOT #6
 2011-08-30 10:33

 MOT test number
 778772241243

Result ✓ Passed

MOT #5 2010-09-07 16:30

MOT test number 254160950213

Result ✓ Passed

MOT #4 2009-09-02 16:26

MOT test number 693375349247

Result \(\sqrt{Passed} \)

MOT #3 2009-09-01 11:45

MOT test number 860464749253

Result × Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Notice Nail in offside front tyre

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 10/18



report date: 2024-03-29

MOT #2

MOT test number

870216448299

Result

Notice Front tyres worn to 3mm on outer edges.

MOT #1

MOT test number

Result

Advice Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

CarCheck.co.uk page 11/18



report date: 2024-03-29

3 July 2024

Tax & MOT check

MOT expiry date



Full MOT history See MOT history

CarCheck.co.uk page 12/18



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 13/18



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 14/18



Owner history

HD54VDP

report date: 2024-03-29

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

See in this check if this CITROEN had different number plates.

More info >

More info >

CarCheck.co.uk page 15/18



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 16/18



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-09-08
Last registration	2023-07-04
Complete history	See info



Registration #1	2004-09-08	6 mi
Registration #2	2007-09-07	20.678 mi
Registration #3	2008-09-02	30.758 mi
Registration #4	2009-09-01	37.162 mi
Registration #5	2009-09-02	37.162 mi
Registration #6	2010-09-07	47.777 mi
Registration #7	2011-08-30	55.785 mi
Registration #8	2012-09-05	64.270 mi
Registration #9	2012-09-05	64.270 mi
Registration #10	2013-08-30	76.284 mi
Registration #11	2014-09-05	85.080 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		9.70 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 17/18



report date: 2024-03-29

~ ~ .	
とっせっせい	/ ratings
- Jaiei	<i>,</i>
Jaice	,

NCAP rating

Video <u>see crash video</u>

Dimensions & weight

Width	1600 mm
Kerb weight	1415 kg
Max. allowed weight	2315 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	DYPY4008633

CarCheck.co.uk page 18/18