



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I30 COMFORT
Colour	White
Year of manufacture	2011
Top speed	116 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	142 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-02-18
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	8
Total items failed	8

MOT #13	2024-02-13 09:21
MOT test number	137549164028
Result	✓ Passed
Next expiry date	2025-02-18
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))

MOT #12	2023-02-01 08:59
MOT test number	227235955552
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11	2022-02-19 12:10
MOT test number	374724777682
Result	✓ Passed

MOT #10	2022-02-14 10:51
MOT test number	804718590103
Result	✗ Failed
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Oil leaking continuously from engine posing a serious risk to road safety (8.4.1 (a) (ii))

**MOT #9** 2021-02-18 11:52**MOT test number** 325313061455**Result** Passed**MOT #8** 2021-02-18 11:52**MOT test number** 157122920227**Result** Failed**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #7** 2019-03-12 10:55**MOT test number** 958287177806**Result** Passed**MOT #6** 2019-03-12 09:41**MOT test number** 800281936450**Result** Failed**Fail** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))**Advice** Nearside Front wheel arch trim catching wheel**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #5** 2018-01-06 12:33**MOT test number** 837955410194**Result** Passed**Advice** Exhaust has a minor leak of exhaust gases front flexi pipe (7.1.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2018-01-05 09:12**MOT test number** 121986810819**Result** ✗ Failed**Advice** Exhaust has a minor leak of exhaust gases front flexi pipe (7.1.2)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2016-12-06 10:40**MOT test number** 596395577668**Result** ✓ Passed**MOT #2** 2015-12-23 16:29**MOT test number** 176028280437**Result** ✓ Passed**MOT #1** 2014-11-28 11:59**MOT test number** 776402934358**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
18 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	18 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-12-01
Last registration	2024-02-13
Complete history	See info



Registration #1	2011-12-01	12 mi
Registration #2	2014-11-28	44.697 mi
Registration #3	2015-12-23	59.024 mi
Registration #4	2016-12-06	72.704 mi
Registration #5	2018-01-05	85.895 mi
Registration #6	2018-01-06	85.896 mi
Registration #7	2019-03-12	94.156 mi
Registration #8	2019-03-12	94.156 mi
Registration #9	2019-03-12	94.156 mi
Registration #10	2019-03-12	94.156 mi
Registration #11	2019-03-12	94.156 mi
Registration #12	2019-03-12	94.156 mi
Registration #13	2019-03-12	94.156 mi
Registration #14	2019-03-12	94.156 mi
Registration #15	2019-03-12	94.156 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1775 mm
Height	1480 mm
Length	4280 mm
Wheel base	2650 mm
Kerb weight	1293 kg
Max. allowed weight	1720 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	G4FABZ349089
---------------	--------------