





report date: 2024-03-28

General information

Make	AUDI
Model	S3 S3 QUATTRO
Colour	Blue
Year of manufacture	2002
Top speed	151 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	221 BHP
Max. torque	280 Nm at 2.200 rpm
Engine capacity	1.781 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	21.6 mpg
Consumption combined	39.8 mpg
CO2 emission	226 g/km
CO2 label	L



CarCheck.co.uk page 1/17



Internet history

Entry 1

Date 2021-01-27


Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/17



report date: 2024-03-28

MOT history

MOT expiry date	2024-06-20
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	79
Total items failed	16

MOT #25	2023-06-21 08:39
MOT test number	312931648746
Result	✓ Passed
Next expiry date	2024-06-20
Advice Brake pipe corroded, covered in grease or other material rear pipes in (c))	n places corroding (1.1.11

MOT #24	2023-06-20 11:28
MOT test number	123814759831
Result	× Failed
Advice Brake pipe corroded, covered in grease or other material rear pipes in place (c))	ces corroding (1.1.11
Fail Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress (5.3.4 (b) (ii))	of dirt drop link boot

MOT #23		2022-06-06 11:22
MOT test	number	768451591271
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing tread crackin	g 225/45/17 (5.2.3 (d)
Advice covered in	Brake pipe corroded, covered in grease or other material both front to regrease eccetra (1.1.11 (c))	ars at rear and rear pipes

CarCheck.co.uk page 3/17



report date: 2024-03-28

MOT #22 2021-06-19 12:12

MOT test number 758542359424

Result ✓ Passed

Advice Brake pipe corroded, covered in grease or other material front to rear & both rear brake pipes been treated with grease (1.1.11 (c))

Advice Sill covers fitted

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Side repeater slightly discoloured (4.4.3 (a))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated had previous repair to boot (6.1.7 (g) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #21 2020-06-02 10:57

MOT test number 277309199591

Result \(\sqrt{Passed} \)

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/17



MOT #20 2020-06-02 10:57

MOT test number 325938054050

Result X Failed

Pass with rectification Battery insecure and likely to cause a short circuit (4.13 (a) (ii))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19 2018-10-11 13:26

MOT test number 917278826082

Result
✓ Passed

Advice Front Power steering pipe/hose has slight seepage (2.1.5 (a))

Advice Headlamp has a product on the lens but not seriously reducing light output both lens discoloured (4.1.4 (b))

Advice Engine cover and Undertrays fitted

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Brake pipe corroded, covered in grease or other material Various (1.1.11 (c))

CarCheck.co.uk page 5/17



report date: 2024-03-28

MOT #18 2018-10-10 13:34 **MOT** test number 377302598585 Result × Failed **Advice** Engine cover and Undertrays fitted **Advice** Front Power steering pipe/hose has slight seepage (2.1.5 (a)) **Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) Fail **Advice** Brake pipe corroded, covered in grease or other material Various (1.1.11 (c)) **Advice** Headlamp has a product on the lens but not seriously reducing light output both lens discoloured (4.1.4 (b)) Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

 MOT #17
 2017-09-20 16:07

 MOT test number
 872675388981

 Result
 ✓ Passed

MOT #16 2017-09-13 15:50

MOT test number 785454035278

Result X Failed

Fail Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Headlamp aim beam image obviously incorrect both, due to lens clouded over (1.8.A.1b)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Nearside Rear Headlamp levelling device obviously defective linkage broken (1.7.2)

CarCheck.co.uk page 6/17



✓ Passed

MOT #15 2016-10-13 13:53

455500412576 **MOT** test number

Result ✓ Passed

Advice Front Headlamp deteriorated but light output not reduced both (1.7.5a)

MOT #14 2015-09-01 14:14

MOT test number 943732113681

Front Tyre worn close to the legal limit Both heavily worn on inner edges (4.1.E.1)

Engine light on

Advice Engine cover and undertrays fitted

Advice Oil leak

Result

Advice

Advice

2015-09-01 10:28 **MOT #13**

MOT test number 274340357672

Result × Failed

Advice Front Tyre worn close to the legal limit Both heavily worn on inner edges (4.1.E.1)

Advice Engine cover and undertrays fitted

Oil leak Advice

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Engine light on

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 7/17



report date: 2024-03-28

MOT #12

MOT test number

759045544205

Result

Notice Oil leak

Notice O/s/f tyre scrubbing on inner edge

MOT #11

MOT test number

827974444218

Result

X Failed

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

Notice Oil leak

Fail Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

Notice O/s/f tyre scrubbing on inner edge

MOT #10		2013-09-04 16:24
MOT test	number	718627143201
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.	5.1i)
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice (2.5.C.1a)	Nearside Front constant velocity joint gaiter deteriorated, but preventing the in-	gress of dirt
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5	.1i)

CarCheck.co.uk page 8/17



Advice

HN52TKC

report date: 2024-03-28

MOT #9 2013-09-03 13:49 **MOT** test number 965166243239 Result × Failed Fail Nearside Rear Shock absorber has an excessively worn bush (2.7.4) Advice Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a) Under-trays fitted obscuring some underside components Notice **Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g) Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Offside Stop lamp not working (1.2.1b) Fail Windscreen washer provides insufficient washer liquid (8.2.3) Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g) Notice Engine covers fitted obscuring some components in the engine bay

MOT #8		2012-09-03 13:50
MOT test	number	389627442496
Result		✓ Passed
Advice	Nearside Front constant velocity joint gaiter damaged, but preventing the in	ngress of dirt (2.5.C.1a)
Notice	Under-trays fitted obscuring some underside components	
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Nail in offside front tyre	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Engine covers fitted obscuring some components in the engine bay	

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 9/17



report date: 2024-03-28

MOT #7

MOT test number

Result

Notice Both front and rear brake disc's are starting to wear down

MOT #6

MOT test number

Fesult

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Rear brake discs pitted

MOT #5

MOT test number

613221060049

Result

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 10/17



report date: 2024-03-28

MOT #4 2009-03-18 11:05 **MOT** test number 900677879096 ✓ Passed Result **Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f) Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Notice Rear discs corroded Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a) Advice Rear Brake pad(s) wearing thin (3.5.1g) Advice Rear Tyre worn close to the legal limit (4.1.E.1) Notice Srevice light on in 100 miles Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3		2008-03-15 10:12
MOT test r	number	433475178039
Result		✓ Passed
Advice	Nearside Rear brake disc slightly pitted (3.5.1h)	
Advice (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not resulting	in excessive movement
Advice	Offside Rear brake disc slightly pitted (3.5.1h)	

Advice Offside Rear brake disc slightly pitted (3.5.1h)	
MOT #2	2007-03-21 11:48
MOT test number	600980587063
Result	✓ Passed
MOT #1	2006-01-05 11:00
MOT test number	913195206082
Result	✓ Passed

CarCheck.co.uk page 11/17



Tax & MOT check



Tax status	Valid until 1 May
Days left	2
MOT expiry date	20 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 12/17



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 13/17



Owner history

o mile motory	
For how long did the current and previous owner(s) have this AUDI? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
manage of the same	

manuse and the same and the sam	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	UK UK
Finite since	mn.n.n
Current registration	UK NE
Finite since	mm.m.m
	More info >

CarCheck.co.uk page 14/17



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 15/17



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2002-12-31
Last registration	2023-06-21
Complete history	See info



Registration #2 2006-01-05 29.917 mi Registration #3 2007-03-21 41.976 mi Registration #4 2008-03-15 53.936 mi Registration #5 2009-03-18 61.664 mi Registration #6 2010-03-02 64.743 mi Registration #7 2010-08-26 55.144 mi Registration #8 2011-09-05 74.490 mi Registration #9 2012-09-03 83.177 mi Registration #10 2013-09-03 92.386 mi Registration #11 2013-09-04 92.390 mi Registration #12 2014-09-01 99.888 mi Registration #13 2014-09-02 99.888 mi Registration #15 Registration #16 Registration #17 Registration #18 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21 Registration #22 Registration #24 Registration #25 Registration #25 Registration #26			
Registration #3 2007-03-21 41.976 mi Registration #4 2008-03-15 53.936 mi Registration #4 2008-03-15 53.936 mi Registration #5 2009-03-18 61.664 mi Registration #6 2010-03-02 64.743 mi Registration #6 2010-08-26 65.144 mi Registration #8 2011-09-05 74.490 mi Registration #8 2011-09-05 74.490 mi Registration #9 2012-09-03 83.177 mi Registration #10 2013-09-03 92.386 mi Registration #11 2013-09-04 92.390 mi Registration #11 2013-09-04 92.390 mi Registration #12 2014-09-01 99.888 mi Registration #13 2014-09-02 99.888 mi Registration #14 2015-09-01 106.606 mi Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #19 Registration #19 Registration #20 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #25 Registration #25 Registration #26	Registration #1	2002-12-31	28 mi
Registration #4 2008-03-15 53,936 mi Registration #5 2009-03-18 61.664 mi Registration #6 2010-03-02 64.743 mi Registration #7 2010-08-26 55.144 mi Registration #8 2011-09-05 74.490 mi Registration #9 2012-09-03 83.177 mi Registration #10 2013-09-03 92.386 mi Registration #11 2013-09-04 92.390 mi Registration #12 2014-09-01 99.888 mi Registration #13 2014-09-02 99.888 mi Registration #14 2015-09-01 106.606 mi Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #20 Registration #21 Registration #22 Registration #24 Registration #25 Registration #26	Registration #2	2006-01-05	29.917 mi
Registration #5 2009-03-18 61.664 mi Registration #6 2010-03-02 64.743 mi Registration #7 2010-08-26 65.144 mi Registration #8 2011-09-05 74.490 mi Registration #9 2012-09-03 83.177 mi Registration #10 2013-09-03 92.386 mi Registration #11 2013-09-04 92.390 mi Registration #12 2014-09-01 99.888 mi Registration #13 2014-09-02 99.888 mi Registration #14 2015-09-01 106.606 mi Registration #15 Registration #15 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #25 Registration #25 Registration #25 Registration #25 Registration #26	Registration #3	2007-03-21	41.976 mi
Registration #6 2010-03-02 64.743 mi Registration #7 2010-08-26 65.144 mi Registration #8 2011-09-05 74.490 mi Registration #9 2012-09-03 83.177 mi Registration #10 2013-09-03 92.386 mi Registration #11 2013-09-04 92.390 mi Registration #12 2014-09-01 99.888 mi Registration #13 2014-09-02 99.888 mi Registration #14 2015-09-01 106.606 mi Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #22 Registration #23 Registration #24 Registration #24 Registration #25 Registration #25 Registration #26	Registration #4	2008-03-15	53.936 mi
Registration #7 2010-08-26 65.144 mi Registration #8 2011-09-05 74.490 mi Registration #9 2012-09-03 83.177 mi Registration #10 2013-09-03 92.386 mi Registration #11 2013-09-04 92.390 mi Registration #12 2014-09-01 99.888 mi Registration #13 2014-09-02 99.888 mi Registration #14 2015-09-01 106.606 mi Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #22 Registration #24 Registration #25 Registration #25 Registration #25 Registration #25 Registration #26	Registration #5	2009-03-18	61.664 mi
Registration #8 2011-09-05 74.490 mi Registration #9 2012-09-03 83.177 mi Registration #10 2013-09-03 92.386 mi Registration #11 2013-09-04 92.390 mi Registration #12 2014-09-01 99.888 mi Registration #13 2014-09-02 99.888 mi Registration #14 2015-09-01 106.606 mi Registration #15 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #25 Registration #26	Registration #6	2010-03-02	64.743 mi
Registration #9	Registration #7	2010-08-26	65.144 mi
Registration #10 2013-09-03 92.386 mi Registration #11 2013-09-04 92.390 mi Registration #12 2014-09-01 99.888 mi Registration #13 2014-09-02 99.888 mi Registration #14 2015-09-01 106.606 mi Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26	Registration #8	2011-09-05	74.490 mi
Registration #11 2013-09-04 92.390 mi Registration #12 2014-09-01 99.888 mi Registration #13 2014-09-02 99.888 mi Registration #14 2015-09-01 106.606 mi Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26	Registration #9	2012-09-03	83.177 mi
Registration #12 2014-09-01 99.888 mi Registration #13 2014-09-02 99.888 mi Registration #14 2015-09-01 106.606 mi Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26	Registration #10	2013-09-03	92.386 mi
Registration #13 2014-09-02 99.888 mi Registration #14 2015-09-01 106.606 mi Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26	Registration #11	2013-09-04	92.390 mi
Registration #14 2015-09-01 106.606 mi Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26	Registration #12	2014-09-01	99.888 mi
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21 Registration #22 Registration #22 Registration #25 Registration #24 Registration #25 Registration #26	Registration #13	2014-09-02	99.888 mi
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26	Registration #14	2015-09-01	106.606 mi
Registration #16 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #25 Registration #26	Registration #15		11.777 es
Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26	Registration #16		11.777 es
Registration #19 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26	Registration #17		11.777 es
Registration #20 Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26	Registration #18		11.777 es
Registration #21 Registration #22 Registration #23 Registration #24 Registration #25 Registration #26	Registration #19		11.777 es
Registration #22 Registration #23 Registration #24 Registration #25 Registration #26	Registration #20		11.777 es
Registration #23 Registration #24 Registration #25 Registration #26	Registration #21		11.117 es
Registration #24 Registration #25 Registration #26	Registration #22		11.777 es
Registration #25 Registration #26	Registration #23		11.777 es
Registration #26	Registration #24		11.777 46
-	Registration #25		11.777 es
CarCheck.co.uk page 16/17	Registration #26		11.777 es
	CarCheck.co.uk		page 16/17

More info >



report date: 2024-03-28

Car features

50225	Air conditioning
60295	
0482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1904 mm
Height	1415 mm
Length	4159 mm
Wheel base	2519 mm
Kerb weight	1420 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number CarCheck.co.uk	BAM 037674 page 17/17