



report date: 2024-03-28

General information

Make	SUZUKI
Model	JIMNY SZ4
Colour	Grey
Year of manufacture	2011
Top speed	84 mph
0 - 60 mph	17.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	85 BHP
Max. torque	110 Nm at 4.100 rpm
Engine capacity	1.328 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.7 mpg
CO2 emission	167 g/km
CO2 label	H







Internet history

Entry 1

Date	2021-06-10
Pictures	26
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-19
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	6
Total items failed	0

MOT #13	2023-07-20 16:09
MOT test number	422578037275
Result	✓ Passed
Next expiry date	2024-07-19

MOT #12	2022-06-15 08:39
MOT test number	147032822076
Result	✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material as marked (1.1.11 (c))

MOT #11	2021-06-15 08:22
MOT test number	560491699959
Result	✓ Passed

MOT #10	2021-06-14 15:16
MOT test number	685918113578
Result	✗ Failed
MAJOR	Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
MAJOR	Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MOT #9** 2021-04-30 11:48**MOT test number** 514853796918**Result** ✓ Passed**MOT #8** 2020-07-28 09:03**MOT test number** 286886857604**Result** ✓ Passed**MOT #7** 2019-07-18 15:19**MOT test number** 879361889423**Result** ✓ Passed**MOT #6** 2019-07-17 13:59**MOT test number** 963053856333**Result** ✗ Failed**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #5** 2018-08-09 13:54**MOT test number** 657425544082**Result** ✓ Passed**MOT #4** 2017-11-17 09:13**MOT test number** 325090200324**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2016-11-25 09:40**MOT test number** 669277607376**Result** ✓ Passed



MOT #2	2015-12-07 09:20
MOT test number	362899557224
Result	✓ Passed

MOT #1	2014-11-14 08:54
MOT test number	736688614366
Result	✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
19 July 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	19 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	KV61UJE
Plate since	2019-03-28
Current registration	KV61UJE
Plate since	2019-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-12-14
Last registration	2023-07-20
Complete history	See info



Registration #1	2011-12-14	15 mi
Registration #2	2014-11-14	10.491 mi
Registration #3	2015-12-07	14.185 mi
Registration #4	2016-11-25	17.603 mi
Registration #5	2017-11-17	20.874 mi
Registration #6	2018-08-09	23.004 mi
Registration #7	2019-07-17	27.248 mi
Registration #8	2019-07-18	27.249 mi
Registration #9	2019-07-19	27.250 mi
Registration #10	2019-07-20	27.251 mi
Registration #11	2019-07-21	27.252 mi
Registration #12	2019-07-22	27.253 mi
Registration #13	2019-07-23	27.254 mi
Registration #14	2019-07-24	27.255 mi
Registration #15	2019-07-25	27.256 mi

More info >



Dimensions & weight

Width	1600 mm
Height	1705 mm
Length	3695 mm
Wheel base	2250 mm
Kerb weight	1150 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M13A-2267320