



report date: 2024-03-29

General information

Make	FORD
Model	FIESTA EDGE
Colour	Black
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm at 4.200 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-15
Pictures	4
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-03
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	41
Total items failed	30

MOT #20	2024-04-03 16:01
MOT test number	699010385814
Result	✓ Passed
Next expiry date	2025-04-03
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #19**

2024-04-02 10:54

**MOT test number**

814020352580

**Result****✗ Failed****Fail**

Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**Advice**

Nearside Front Play in steering rack inner joint(s)

**Fail**

Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Fail**Road wheel fixings not compatible all 4 wheels nuts are the incorrect nuts for the wheels  
nsf,osf,osr,nsr (5.2.2 (d))**Fail**

Nearside Front Direction indicator incorrect colour (4.4.3 (a))

**Advice**

Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice**

Offside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Fail**

Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))

**MOT #18**

2023-03-31 11:53

**MOT test number**

138602001414

**Result****✓ Passed****Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Central Front Exhaust mounting defective (6.1.2 (a))

**Advice**

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice**

Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #17** 2022-04-04 13:48**MOT test number** 806175596641**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #16** 2021-05-12 08:32**MOT test number** 660915099328**Result** ✓ Passed**MOT #15** 2021-05-06 09:55**MOT test number** 966641882655**Result** ✗ Failed**Fail** Offside Front Lower Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases Flexi pipe (6.1.2 (a))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #14** 2020-05-18 11:00**MOT test number** 300027599135**Result** ✓ Passed

**MOT #13** 2020-05-13 10:17**MOT test number** 966529205806**Result** ✗ Failed

- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Undertray likely to become detached (6.2.1 (a) (ii))

**MOT #12** 2019-05-23 10:03**MOT test number** 658783488762**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2019-05-18 15:15**MOT test number** 900142777940**Result** ✗ Failed

- Fail** Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #10** 2018-04-07 10:15**MOT test number** 461094428350**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases back box (7.1.2)**Advice** Windscreen is cracked**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**Advice** Rear Direction indicator slightly discoloured both (1.4.A.2f)**Advice** Exhaust heat shield is loose**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2017-04-27 08:34**MOT test number** 887474504003**Result** ✓ Passed**MOT #8** 2016-04-29 10:27**MOT test number** 944320882947**Result** ✓ Passed**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Front tyres worn on inner edges**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2016-04-29 10:27**MOT test number** 841081808264**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Front tyres worn on inner edges**MOT #6** 2015-04-20 15:24**MOT test number** 535680015168**Result** ✓ Passed**Notice** Slight brake bind from front brakes**MOT #5** 2015-04-20 12:32**MOT test number** 279270915194**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Notice** Slight brake bind from front brakes**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Road wheel bead rim badly distorted (4.2.A.1a)



**MOT #4** 2014-04-04 12:06**MOT test number** 959484094004**Result** ✓ Passed**Notice** Exhaust heat shield loose**MOT #3** 2014-04-04 10:17**MOT test number** 108894494467**Result** ✗ Failed**Notice** Exhaust heat shield loose**Fail** Brake pedal spongy (3.3.B.1b)**MOT #2** 2013-04-04 14:21**MOT test number** 228714993052**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-04-03 10:53**MOT test number** 188823893042**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Brake pedal spongy (3.3.B.1b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
3 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	3 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2010-04-30
Last registration	2024-04-03
Complete history	<a href="#">See info</a>



Registration #1	2010-04-30	27 mi
Registration #2	2013-04-03	56.430 mi
Registration #3	2013-04-04	56.430 mi
Registration #4	2014-04-04	65.708 mi
Registration #5	2014-04-04	65.708 mi
Registration #6	2015-04-20	75.496 mi
Registration #7	2015-04-20	75.496 mi
Registration #8	2016-04-29	87.971 mi
Registration #9	2016-04-29	87.971 mi
Registration #10	2017-04-27	105.769 mi
Registration #11	2018-04-07	122.595 mi
Registration #12	2019-04-07	139.421 mi
Registration #13	2020-04-07	156.247 mi
Registration #14	2021-04-07	173.073 mi
Registration #15	2022-04-07	189.899 mi
Registration #16	2023-04-07	206.725 mi
Registration #17	2024-04-03	223.551 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		
Registration #22		

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	AU64848