



NH08TZK

report date: 2024-03-29

General information

Make	FORD
Model	FUSION STYLE 110
Colour	Blue
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg





Internet history

Entry 1

Date	2021-06-06
Pictures	20
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #21	2023-05-26 16:11
MOT test number	471735482962
Result	✓ Passed
Next expiry date	2024-06-02
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #20	2023-05-26 16:11
MOT test number	160156137796
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))

MOT #19	2022-06-01 15:46
MOT test number	931012966986
Result	✓ Passed
Advice	Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2022-06-01 15:46

MOT test number

375160847137

Result**✗ Failed****Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Pass with rectification** Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MOT #17**

2021-06-03 15:00

MOT test number

785828639426

Result**✓ Passed****MOT #16**

2021-05-26 09:11

MOT test number

244343814126

Result**✗ Failed****Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #15**

2020-05-18 10:47

MOT test number

668290820665

Result

✓ Passed

- Advice** Internal rear view mirror missing
- Advice** Slight oil leak from gearbox
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Offside rear light cluster has water ingress

MOT #14

2019-05-15 13:26

MOT test number

665853829114

Result

✓ Passed

- Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Lower Gearbox mounting defective

MOT #13

2019-05-15 08:16

MOT test number

170304312867

Result

✗ Failed

- Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Rear Lower Gearbox mounting defective
- Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Fail** Offside Rear Stop lamp(s) light intensity significantly reduced bulb fitted incorrectly (4.3.3 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2018-04-26 08:29**MOT test number** 463097032930**Result** ✓ Passed**Advice** EML Light illuminated**Advice** Front Brake pad(s) wearing thin Approx 80% worn (3.5.1g)**MOT #11** 2017-05-23 09:28**MOT test number** 938410803619**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Rear Lower engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)**MOT #10** 2017-05-23 09:28**MOT test number** 700182968801**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**Advice** Rear Lower engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #9** 2016-05-24 08:24**MOT test number** 927717368365**Result** ✓ Passed**Advice** Nearside Rear wheel bearing has slight roughness when rotated

**MOT #8** 2016-05-24 07:35**MOT test number** 761527725712**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm outer 3/4 of tread (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Tyre worn close to the legal limit outer 3/4 of tread (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #7** 2015-05-13 16:15**MOT test number** 657763435187**Result** ✓ Passed**Notice** Rear exhaust box in poor condition**Notice** Front brake discs in poor condition on inner face**MOT #6** 2014-05-23 08:45**MOT test number** 328403744166**Result** ✓ Passed**Notice** Rear exhaust silencer deteriorating**MOT #5** 2013-05-22 17:18**MOT test number** 969622143112**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2013-05-22 15:43**MOT test number** 225342643463**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-05-22 11:45**MOT test number** 298843142182**Result** ✓ Passed**MOT #2** 2011-05-25 12:00**MOT test number** 476075441154**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-05-25 12:00**MOT test number** 199375841177**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-06-30
Last registration	2023-05-26
Complete history	See info



Registration #1	2008-06-30	19 mi
Registration #2	2011-05-25	20.244 mi
Registration #3	2012-05-22	26.576 mi
Registration #4	2013-05-22	36.677 mi
Registration #5	2013-05-22	36.677 mi
Registration #6	2014-05-23	54.357 mi
Registration #7	2015-05-13	68.322 mi
Registration #8	2016-05-24	80.347 mi
Registration #9	2016-05-24	80.347 mi
Registration #10	2017-05-23	92.348 mi
Registration #11	2017-05-23	92.348 mi
Registration #12	2018-05-23	104.349 mi
Registration #13	2018-05-23	104.349 mi
Registration #14	2019-05-23	116.350 mi
Registration #15	2019-05-23	116.350 mi
Registration #16	2020-05-23	128.351 mi
Registration #17	2020-05-23	128.351 mi
Registration #18	2021-05-23	140.352 mi
Registration #19	2021-05-23	140.352 mi
Registration #20	2022-05-23	152.353 mi
Registration #21	2022-05-23	152.353 mi
Registration #22	2023-05-26	164.354 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1376 kg
Max. allowed weight	1795 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8R05782