



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI DSG
Colour	Grey
Year of manufacture	2009
Top speed	117 mph
0 - 60 mph	11.3 seconds
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	123 g/km
CO2 label	D





MOT history

MOT expiry date	2020-10-22
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	21
Total items failed	11

MOT #11	2019-04-23 10:38
MOT test number	906180400015
Result	✓ Passed
Next expiry date	2020-10-22
Advice	Both front tyres wearing on outer edge
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #10	2018-05-31 11:40
MOT test number	723927877468
Result	✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #9** 2018-05-31 09:48**MOT test number** 709411785798**Result** ✗ Failed

- Fail** Offside Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #8 2017-04-04 11:48**MOT test number** 130436354100**Result** ✓ Passed

- Advice** Offside Rear tyre inner edge slightly out of shape

MOT #7 2017-04-04 09:45**MOT test number** 280164285415**Result** ✗ Failed

- Advice** Offside Rear tyre inner edge slightly out of shape
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Front Inner Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Nearside Front Inner Tyre worn close to the legal limit edge worn smooth (4.1.E.1)

MOT #6 2016-04-01 09:48**MOT test number** 380442555967**Result** ✓ Passed

- Advice** Nearside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)
- Advice** Offside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)

**MOT #5**

2016-03-31 14:06

MOT test number

467679632390

Result**✗ Failed****Advice** Nearside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4**

2014-11-27 11:39

MOT test number

177961234305

Result**✓ Passed****Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**MOT #3**

2013-10-31 14:30

MOT test number

465514903355

Result**✓ Passed****Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #2	2013-10-31 12:54
MOT test number	415644603478
Result	✗ Failed
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Front registration plate delaminated but not likely to be misread (6.3.1d)
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #1	2012-11-30 11:27
MOT test number	636585132326
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KN59NBD
Plate since	2019-09-29
Current registration	 KN59NBD
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-09-30
Last registration	2019-04-23
Complete history	See info



Registration #1	2009-09-30	10 mi
Registration #2	2012-11-30	38.862 mi
Registration #3	2013-10-31	51.999 mi
Registration #4	2013-10-31	52.001 mi
Registration #5	2014-11-27	72.179 mi
Registration #6	2016-03-31	96.120 mi
Registration #7	2019-04-23	120.171 mi
Registration #8	2019-04-23	120.171 mi
Registration #9	2019-04-23	120.171 mi
Registration #10	2019-04-23	120.171 mi
Registration #11	2019-04-23	120.171 mi
Registration #12	2019-04-23	120.171 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1266 kg
Max. allowed weight	1890 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	CAY 131140