





report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T3
Colour	Grey
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	129 Nm at 4.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.5 mpg
Consumption combined	42.1 mpg



CarCheck.co.uk page 1/11



MOT history

MOT #18	2020-05-18 13:53
MOT test number	504309539640

Next expiry date 2021-05-17

MOT #17 2019-05-08 08:30

MOT test number 294703092097

MOT #16 2018-04-20 11:16

MOT test number 359735776820

Advice Offside Fuel tank strap corroded.

Advice Nearside Rear Tyre perishing.

MOT #15 2017-05-17 09:53

MOT test number 904833948206

Result \(\sqrt{Passed} \)

Advice Offside Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Rear Brake binding

Advice Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)

Advice Nearside Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Rear Brake binding

Advice Nearside Front Lower Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Rear Brake hose slightly deteriorated (3.6.B.4d)

MOT #14 2016-06-09 15:09

MOT test number 718537384185

CarCheck.co.uk page 2/11



MOT #13 2015-06-01 15:10

MOT test number 256862255173

MOT #12 2015-05-29 13:01

MOT test number 299209045178

Result X Failed

Fail Offside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)

Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Nearside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Notice O/S/R Tyre very perrished

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #11 2014-05-20 13:34

MOT test number 376570244169

Result
✓ Passed

Advice Offside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

Advice Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output

(1.7.5a)

MOT #10 2013-06-04 12:29

MOT test number 716155353114

CarCheck.co.uk page 3/11



MOT #9		2012-06-19 09:29
MOT test	number	159261072159
Result		✓ Passed
MOT #8		2011-06-20 13:08
MOT test	number	547431771184
Result		✓ Passed
Advice	Front Direction indicators slightly discoloured (1.4.A.2f)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2010-04-30 12:13
MOT test number	890940320173
Result	✓ Passed
MOT #6	2009-05-05 17:38
MOT test number	313995229182
Result	✓ Passed
Notice Offside rear tyre starting to run out of shape	

CarCheck.co.uk page 4/11



MOT #5 2009-05-05 10:08 **MOT test number** 912885129173 Result **X** Failed **Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g) Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b) Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g) Notice Offside rear tyre starting to run out of shape Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b) Fail Rear brake application uneven (3.7.B.2)

MOT #4		2008-05-06 15:02
MOT test number		883147228159
Result		× Failed
Pass with rectification	Offside Headlamp aim too high (1.8)	
Pass with rectification	Nearside Headlamp aim too high (1.8)	

Pass with rectification	Nearside Headlamp aim too high (1.8)	
MOT #3		2008-05-06 15:02
MOT test number		214047928120
Result		✓ Passed
MOT #2		2007-05-01 14:02
MOT test number		703941527174
Result		✓ Passed
MOT #1		2006-04-28 16:00
MOT test number		102008016116
Result		✓ Passed


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
THE STATE OF THE S	

THE STREET STREET	
HARMAN AND AND AND AND AND AND AND AND AND A	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK NA
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2002-04-18
Last registration	2020-05-18
Complete history	See info



Registration #1	2002-04-18	17 mi
Registration #2	2006-04-28	17.138 mi
Registration #3	2007-05-01	25.248 mi
Registration #4	2008-05-06	31.280 mi
Registration #5	2009-05-05	35.423 mi
Registration #6	2009-05-05	35.423 mi
Registration #7	2010-04-30	40.318 mi
Registration #8	2011-06-20	47.305 mi
Registration #9	2012-06-19	49.312 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.117 es

More info >

page 10/11 CarCheck.co.uk



Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1205 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	4ZZU342490 page 11/11