



report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-25
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	23
Total items failed	8

MOT #15	2024-04-26 12:13
MOT test number	466254135275
Result	✓ Passed
Next expiry date	2025-04-25

MOT #14	2023-10-19 08:33
MOT test number	294324287160
Result	✓ Passed

MOT #13	2022-10-12 13:19
MOT test number	169492565469
Result	✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #12**

2022-10-12 11:05

MOT test number

245161219942

Result

✗ Failed

Advice

Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

Fail

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail

Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail

Nearside Parking brake inoperative on one side (1.4.1 (a))

MOT #11

2021-06-08 10:10

MOT test number

462045794397

Result

✓ Passed

Advice

Tyre slightly damaged/cracking or perishing all tyres perished slightly (5.2.3 (d) (ii))

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #10

2020-10-08 13:51

MOT test number

527167417769

Result

✓ Passed

MOT #9

2019-04-16 12:00

MOT test number

660514015282

Result

✓ Passed

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8** 2018-04-10 10:03**MOT test number** 268508472558**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2017-04-24 10:25**MOT test number** 721680944791**Result** ✓ Passed**MOT #6** 2016-04-12 08:23**MOT test number** 647384550936**Result** ✓ Passed**Advice** Exhaust corroded and rear clamp missing**Advice** Nearside Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear wiper not working**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2016-04-12 08:23**MOT test number** 394428982528**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Rear wiper not working**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Exhaust corroded and rear clamp missing**MOT #4** 2015-04-15 15:50**MOT test number** 439885705102**Result** ✓ Passed**MOT #3** 2014-04-23 11:52**MOT test number** 879173214192**Result** ✓ Passed**MOT #2** 2013-04-16 14:33**MOT test number** 559886503100**Result** ✓ Passed



MOT #1	2013-04-16 08:29
MOT test number	715436203104
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
25 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	25 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	FJ10XOA
Plate since	2019-03-28
Current registration	FJ10XOA
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-11-01
Last registration	2024-04-26
Complete history	See info



Registration #1	2010-11-01	9 mi
Registration #2	2013-04-16	26.919 mi
Registration #3	2013-04-16	26.919 mi
Registration #4	2014-04-23	37.576 mi
Registration #5	2015-04-15	41.755 mi
Registration #6	2016-04-12	46.558 mi
Registration #7	2016-04-12	46.558 mi
Registration #8	2017-04-24	51.019 mi
Registration #9	2018-04-10	52.848 mi
Registration #10	2019-04-26	55.377 mi
Registration #11	2019-04-26	55.377 mi
Registration #12	2019-04-26	55.377 mi
Registration #13	2019-04-26	55.377 mi
Registration #14	2019-04-26	55.377 mi
Registration #15	2019-04-26	55.377 mi
Registration #16	2019-04-26	55.377 mi
Registration #17	2019-04-26	55.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5775203