



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI
Colour	Silver
Year of manufacture	2012
Top speed	117 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-05
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-04-03
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	8
Total items failed	11

MOT #14	2024-04-04 15:44
MOT test number	588249633039
Result	✓ Passed
Next expiry date	2025-04-03

MOT #13	2023-03-15 14:38
MOT test number	611435681465
Result	✓ Passed

MOT #12	2023-03-15 12:03
MOT test number	507750962391
Result	✗ Failed

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #11	2022-03-11 09:37
MOT test number	924089369011
Result	✓ Passed



MOT #10	2022-03-11 09:37
MOT test number	262902866362
Result	✗ Failed
<b>Pass with rectification</b>	Rear Reversing lamp inoperative (4.6.1 (a))

MOT #9	2021-03-22 11:08
MOT test number	471457530794
Result	✓ Passed

MOT #8	2021-03-20 09:50
MOT test number	458700758828
Result	✗ Failed
<b>Fail</b>	Front Macpherson strut has an unsafe modification both leaking badly (5.3.3 (c) (i))
<b>Fail</b>	Front Registration plate insecure (0.1 (a))
<b>Fail</b>	Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Offside Windscreen wiper does not clear the windscreen effectively torn (3.4 (b) (ii))

MOT #7	2019-06-13 07:46
MOT test number	841730283992
Result	✓ Passed
<b>Minor</b>	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #6	2019-06-13 07:46
MOT test number	726714223732
Result	✗ Failed
<b>Pass with rectification</b>	Windscreen washer provides insufficient washer liquid (3.5 (a))
<b>Pass with rectification</b>	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>Minor</b>	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #5** 2018-07-31 11:55**MOT test number** 491786004317**Result** ✓ Passed**MOT #4** 2018-07-31 09:37**MOT test number** 203215695052**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**MOT #3** 2017-06-01 11:45**MOT test number** 143077020385**Result** ✓ Passed**MOT #2** 2016-06-20 12:00**MOT test number** 863405044217**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2015-06-04 11:48**MOT test number** 285265455134**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
3 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	3 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-06-08
Last registration	2024-04-04
Complete history	<a href="#">See info</a>



Registration #1	2012-06-08	25 mi
Registration #2	2015-06-04	37.092 mi
Registration #3	2016-06-20	44.517 mi
Registration #4	2017-06-01	53.284 mi
Registration #5	2018-07-31	63.861 mi
Registration #6	2018-07-31	63.861 mi
Registration #7	2019-06-13	72.142 mi
Registration #8	2019-06-13	72.142 mi
Registration #9	2019-06-13	72.142 mi
Registration #10	2019-06-13	72.142 mi
Registration #11	2019-06-13	72.142 mi
Registration #12	2019-06-13	72.142 mi
Registration #13	2019-06-13	72.142 mi
Registration #14	2019-06-13	72.142 mi
Registration #15	2019-06-13	72.142 mi
Registration #16	2019-06-13	72.142 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1761 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	135730K