



EJ02DPV

report date: 2024-03-29

General information

Make	BMW
Model	Z3
Colour	Black
Year of manufacture	2002
Gearbox	-

Engine & fuel consumption

Engine capacity	1.895 cc
Fuel type	Petrol
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 3


Date	2023-03-28
Pictures	4
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date	2021-10-13
Pictures	40
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-09-24
Pictures	44
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-14
MOT pass rate	70 %
MOT passed	19
Failed MOT tests	8
Total advice items	58
Total items failed	12

MOT #27	2023-11-15 15:56
MOT test number	335550398979
Result	✓ Passed
Next expiry date	2024-11-14
Advice	Central Brake pipe corroded, covered in grease or other material corroding (1.1.11 (c))

MOT #26	2023-11-15 09:19
MOT test number	404408254380
Result	✗ Failed
Advice	Central Brake pipe corroded, covered in grease or other material corroding (1.1.11 (c))
Fail	Central Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #25	2022-10-21 08:28
MOT test number	993419510089
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #24**

2022-10-21 08:28

MOT test number

885434559643

Result**✗ Failed****Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**MOT #23**

2021-11-15 14:15

MOT test number

292688622250

Result**✓ Passed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #22**

2021-06-10 11:04

MOT test number

122958927292

Result**✓ Passed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #21**

2021-06-07 07:58

MOT test number

834875335631

Result**✗ Failed****Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Offside Rear Suspension arm corroded and seriously weakened (5.3.3 (b) (i))

**MOT #20**

2020-05-12 15:04

MOT test number

800667342617

Result

✓ Passed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Rear brake discs surfaces corroded
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Exhaust has a minor leak of exhaust gases front pipe (6.1.2 (a))
- Advice** Front exhaust pipe clamp broken advise replacing
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside rear and offside rear cross member mount bushes worn/ slight movement

MOT #19

2020-05-12 10:16

MOT test number

908761566293

Result

✗ Failed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Front exhaust pipe clamp broken advise replacing
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside rear and offside rear cross member mount bushes worn/ slight movement
- Advice** Exhaust has a minor leak of exhaust gases front pipe (6.1.2 (a))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Rear brake discs surfaces corroded
- Fail** Nearside Rear Tyre has ply or cords exposed bald on inner edge and perishing, cracking cords visible (5.2.3 (d) (ii))

**MOT #18** 2019-05-03 11:41**MOT test number** 684980781474**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #17** 2019-05-01 09:06**MOT test number** 404556599812**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #16** 2018-05-03 09:26**MOT test number** 970778806312**Result** ✓ Passed**Advice** Fuel cap seal slightly perished**MOT #15** 2017-05-18 09:19**MOT test number** 155889683627**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Oil leak gearbox**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Oil leak engine

**MOT #14**

2017-05-18 09:19

MOT test number

367797161928

Result**✗ Failed**

- Advice** Oil leak engine
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Oil leak gearbox
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

MOT #13

2016-05-13 09:23

MOT test number

127578054748

Result**✓ Passed**

- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Offside Rear Tyre worn close to the legal limit on 3mm + perished + split on inner 245/40/17m 91w (4.1.E.1)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Brake pipe slightly corroded front 2 rear x2 (3.6.B.2c)
- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #12** 2015-04-24 09:19**MOT test number** 959634515160**Result** ✓ Passed**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Notice** Both front tyres worn on inner + outer 225/45/17 94w**MOT #11** 2014-05-10 11:32**MOT test number** 208460434119**Result** ✓ Passed**Notice** Of side rear tyre worn on inner**MOT #10** 2014-05-10 09:48**MOT test number** 908190734159**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** Of side rear tyre worn on inner**MOT #9** 2013-05-07 12:51**MOT test number** 877607623130**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #8** 2012-05-05 11:32**MOT test number** 146016322197**Result** ✓ Passed

**MOT #7** 2011-05-13 14:53**MOT test number** 935123131165**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #6** 2010-05-12 13:21**MOT test number** 951422230176**Result** ✓ Passed**MOT #5** 2010-05-11 15:04**MOT test number** 432151730194**Result** ✗ Failed**Fail** Front Exhaust system not adequately supported (7.1.1)**Fail** Front registration plate fitted to the front does not have black characters on a white background (6.3.2a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Rear registration plate fitted to the rear does not have black characters on a yellow background (6.3.2b)**MOT #4** 2009-05-19 09:32**MOT test number** 532039239161**Result** ✓ Passed**MOT #3** 2008-05-22 14:50**MOT test number** 612003848187**Result** ✓ Passed



MOT #2	2007-05-18 17:10
MOT test number	602278037184
Result	✓ Passed

MOT #1	2006-09-30 17:40
MOT test number	284593576203
Result	✓ Passed

Notice FRONT BRAKE PADS GETTING LOW



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
14 November 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	14 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	31
First mileage registration	2002-06-10
Last registration	2023-11-15
Complete history	See info



Registration #1	2002-06-10	16 mi
Registration #2	2006-09-30	20.987 mi
Registration #3	2007-05-18	23.577 mi
Registration #4	2008-05-22	40.077 mi
Registration #5	2009-05-19	54.724 mi
Registration #6	2010-05-11	67.694 mi
Registration #7	2010-05-12	67.735 mi
Registration #8	2011-05-13	73.395 mi
Registration #9	2012-05-05	78.258 mi
Registration #10	2013-05-07	82.881 mi
Registration #11	2014-05-10	85.872 mi
Registration #12	2014-05-10	85.872 mi
Registration #13	2015-04-24	89.349 mi
Registration #14	2016-05-13	92.115 mi
Registration #15	2017-05-18	94.417 mi
Registration #16	2017-05-18	94.417 mi
Registration #17	2018-05-22	95.277 mi
Registration #18	2019-05-22	95.277 mi
Registration #19	2020-05-22	95.277 mi
Registration #20	2021-05-22	95.277 mi
Registration #21	2022-05-22	95.277 mi
Registration #22	2023-05-22	95.277 mi
Registration #23	2023-05-22	95.277 mi
Registration #24	2023-05-22	95.277 mi
Registration #25	2023-05-22	95.277 mi
Registration #26	2023-05-22	95.277 mi

Registration #27	2025-25-25	25,252 442
Registration #28	2025-25-25	25,252 442
Registration #29	2025-25-25	25,252 442
Registration #30	2025-25-25	25,252 442
Registration #31	2025-25-25	25,252 442

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Additional information

Engine number	00749965
---------------	----------