



Mercedes-Benz



KRI4ZTG


report date: 2024-03-29

General information

|                     |                                    |
|---------------------|------------------------------------|
| Make                | MERCEDES-BENZ                      |
| Model               | B-CLASS B180 CDI BLUEEFFICIENCY SE |
| Colour              | Silver                             |
| Year of manufacture | 2014                               |
| Top speed           | 118 mph                            |
| 0 - 100 km/h        | 11.9 seconds                       |
| 0 - 60 mph          | 11.9 seconds                       |
| Gearbox             | 7 speed automatic                  |

Engine & fuel consumption

|                         |                          |
|-------------------------|--------------------------|
| Power                   | 80 kW / 109 HP / 107 BHP |
| Max. torque             | 260 Nm at 1.750 rpm      |
| Engine capacity         | 1.461 cc                 |
| Cylinders               | 4                        |
| Fuel type               | Diesel                   |
| Consumption city        | 57.7 mpg                 |
| Consumption extra urban | 76.4 mpg                 |
| Consumption combined    | 68.9 mpg                 |
| CO2 emission            | 107 g/km                 |
| CO2 label               | B                        |





Internet history


Entry 2

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-08-11                  |
| Pictures      | 0                           |
| Listing price | <a href="#">View report</a> |

source: autotrader.co.uk

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-08-04                  |
| Pictures      | 9                           |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-08-20 |
| MOT pass rate      | 70 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 3          |
| Total advice items | 23         |
| Total items failed | 1          |

|                  |  |
|------------------|--|
| MOT #10          | 2023-08-21 09:50   |
| MOT test number  | 384619184015   |
| Result           | ✓ Passed   |
| Next expiry date | 2024-08-20   |
| Advice           | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice           | Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))               |
| Advice           | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))              |

|                 |   |
|-----------------|---|
| MOT #9          | 2022-08-18 15:53  |
| MOT test number | 962548166278  |
| Result          | ✓ Passed  |
| Advice          | Nearside Rear Nail in tyre  |
| Minor           | Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |

**MOT #8** 2022-08-17 16:21**MOT test number** 475853083452**Result** ✗ Failed

**MAJOR** Nearside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Nearside Rear Nail in tyre

**Minor** Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #7** 2021-08-05 09:18**MOT test number** 986453778878**Result** ✓ Passed**MOT #6** 2020-10-23 16:36**MOT test number** 723887270295**Result** ✓ Passed

**Advice** Emission too low to register

**Advice** Underside tray fitted not allowing for full inspection



|  |  |
|--|--|
| <b>MOT #5</b>  | 2020-10-23 09:25   |
| <b>MOT test number</b>   | 397673339266   |
| <b>Result</b>  | ✗ Failed   |
| <b>DANGEROUS</b> Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))                                    |  |
| <b>MAJOR</b> Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))   |  |
| <b>DANGEROUS</b> Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) |  |
| <b>Advice</b>  | Emission too low to register   |
| <b>Advice</b>  | Front Brake disc worn, pitted or scored, but not seriously weakened has big lipped, may require to attention (1.1.14 (a) (ii)) |
| <b>MAJOR</b> Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))   |  |
| <b>DANGEROUS</b> Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))                                     |  |
| <b>Advice</b>  | Service light is on  |
| <b>Advice</b>  | Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords may require to attention soon (5.2.3 (d) (i))       |
| <b>Advice</b>  | Offside Front Tyre slightly damaged/cracking or perishing and tread depth on 2 mm, may require to attention (5.2.3 (d) (ii))   |
| <b>Advice</b>  | Underside tray fitted not allowing for full inspection   |

|                        |   |
|------------------------|---|
| <b>MOT #4</b>          | 2019-05-01 13:23                                  |
| <b>MOT test number</b> | 300154631919                                      |
| <b>Result</b>          | ✓ Passed  |
| <b>Advice</b>          | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

|                        |                  |
|------------------------|------------------|
| <b>MOT #3</b>          | 2018-04-30 16:24 |
| <b>MOT test number</b> | 428379143300     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #2</b>          | 2017-05-17 10:05 |
| <b>MOT test number</b> | 400918987398     |
| <b>Result</b>          | ✓ Passed         |



|                         |  |
|-------------------------|--|
| MOT #1                  | 2017-05-17 10:05                                 |
| MOT test number         | 571319463401                                     |
| Result                  | ✗ Failed   |
| Pass with rectification | Nearside Headlamp aim too far to the right (1.8) |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
20 August 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 October           |
| <b>Days left</b>        | 155                             |
| <b>MOT expiry date</b>  | 20 August 2024                  |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |                |
|--|----------------|
| <b>Vehicle class</b>                           | 49             |
| <b>Band</b>                                    | B              |
| <b>Single payment (12 months)</b>              | £ 20,00,-      |
| <b>Single six month payment</b>                | Not applicable |
| <b>Total payable by 12 monthly instalments</b> | £ 21,00,-      |



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>XXXXX</b> |
| Plate since          | 2024-03-29   |
| Current registration |  <b>XXXXX</b> |
| Plate since          | 2024-03-29   |

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

|                   |          |          |
|-------------------|----------|----------|
| Finance company   | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type    | REDACTED | REDACTED |
| Agreement term    | REDACTED | REDACTED |
| Agreement number  | REDACTED | REDACTED |
| Contact info      | REDACTED | REDACTED |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 13                       |
| First mileage registration | 2014-06-03               |
| Last registration          | 2023-08-21               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2014-06-03 | 18 mi     |
| Registration #2  | 2017-05-17 | 21.037 mi |
| Registration #3  | 2017-05-17 | 21.037 mi |
| Registration #4  | 2018-04-30 | 25.440 mi |
| Registration #5  | 2019-05-01 | 36.046 mi |
| Registration #6  | 2020-10-23 | 47.680 mi |
| Registration #7  | 2020-10-23 | 47.681 mi |
| Registration #8  | 2023-08-21 | 55.277 mi |
| Registration #9  | 2023-08-21 | 55.277 mi |
| Registration #10 | 2023-08-21 | 55.277 mi |
| Registration #11 | 2023-08-21 | 55.277 mi |
| Registration #12 | 2023-08-21 | 55.277 mi |
| Registration #13 | 2023-08-21 | 55.277 mi |

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 97%                             |
| Children       | 81%                             |
| Pedestrian     | 56%                             |
| Safety systems | 86%                             |
| Overall rating | 85%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 2010 mm |
| Height              | 1557 mm |
| Length              | 4359 mm |
| Wheel base          | 2699 mm |
| Kerb weight         | 1475 kg |
| Max. allowed weight | 2000 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 50 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |

|                 |                |
|-----------------|----------------|
| Number of seats | 5              |
| Number of axles | 2              |
| Engine number   | K9KF451D012872 |