





General information

| Make | VAUXHALL |
|---------------------|-------------------------------|
| Model | CORSA SRI NAV S/S SRI NAV S/S |
| Colour | Silver |
| Year of manufacture | 2019 |
| Top speed | 109 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption


| Power | 89 BHP |
|----------------------|---------------------|
| Max. torque | 130 Nm at 4.000 rpm |
| Engine capacity | 1.398 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption combined | 44.8 mpg |
| CO2 emission | 123 g/km |
| CO2 label | D |





Internet history

| Entry 2 | |
|---------------|-------------|
| Date | 2021-08-19 |
| Pictures | 14 |
| Listing price | View report |



source: heycar.co.uk

| Entry | 1 |
|-------|---|
|-------|---|

Date

Pictures

Listing price

2021-08-14 10

View report



source: autoonline.co.uk



MOT history

| MOT expiry date | 2024-10-03 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 2 |
| Failed MOT tests | 1 |
| Total advice items | 1 |
| Total items failed | 5 |

| MOT #3 | 2023-10-04 13:39 |
|------------------|------------------|
| MOT test number | 548721083264 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-03 |

| MOT #2 | 2 | 023-10-04 12:04 |
|---|---|-----------------|
| MOT test number | | 789006081117 |
| Result | | 🗙 Failed |
| Fail Tyre pressure moni | coring system malfunctioning or obviously inoperative (5.2.3 (h)) | |
| Pass with rectification | Nearside Front Headlamp aim too high (4.1.2 (a)) | |
| Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | | |
| Pass with rectification | Offside Front Headlamp aim too low (4.1.2 (a)) | |
| Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | | |

| MOT #1 | 2022-10-04 13:32 |
|--|------------------|
| MOT test number | 539381512553 |
| Result | ✓ Passed |
| Advice Front tyres worn to outer edges | |



Tax & MOT check

| ✓ Taxed | ✓ MOT |
|------------------------------|----------------------------|
| Tax due: 1 September 2024 | Expires: 3 October 2024 |
| Tax status | Valid until 1 September |
| Days left | 126 |
| MOT expiry date | 3 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------|
| Date | FET A |
| Category | L AMP |
| Туре | |
| Damage 2 | AMPLE |
| Date | 4 |
| Category | AMPL |
| Туре | |

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******** | |
|---|-------------|
| | |
| | |
| *********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | ₩ UK |
| Ender class | |
| | |





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |



DN69VPP report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 6 |
| First mileage registration | 2019-09-30 |
| Last registration | 2023-10-04 |
| Complete history | <u>See info</u> |
| | |



| Registration #1 | 2019-09-30 | 19 mi |
|-----------------|------------|------------|
| Registration #2 | | 11.777 est |
| Registration #3 | | 11.777 esi |
| Registration #4 | | 11.777 est |
| Registration #5 | | 11.777 esi |
| Registration #6 | | 10.200 est |





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 77% |
| Pedestrian | 71% |
| Safety systems | 56% |
| Overall rating | 72% |
| Video | see crash video |



| Dimensions & weight | |
|------------------------|---------------------|
| Width | 1746 mm |
| Height | 1481 mm |
| Length | 4021 mm |
| Max. allowed weight | 1630 kg |
| Additional information | |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | B14XER -19WB8076LDD |