



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 D S
Colour	Silver
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	153 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-12-08
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-27
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	43
Total items failed	3

MOT #20	2023-07-25 15:08
MOT test number	533474150213
Result	✓ Passed
Next expiry date	2024-07-27

MOT #19	2023-07-24 15:34
MOT test number	357335724483
Result	✗ Failed

- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- MAJOR** Offside Front Headlamp aim too high (4.1.2 (a))



MOT #18

2022-07-01 16:13

MOT test number

387203168792

Result

✓ Passed

- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Front Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #17**

2022-06-30 12:35

MOT test number

309271223689

Result**✗ Failed****MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**DANGEROUS** Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**MOT #16**

2021-07-28 16:16

MOT test number

171537019815

Result**✓ Passed****Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))



MOT #15	2021-04-19 11:21
MOT test number	512000333968
Result	✗ Failed
Advice	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
MAJOR	Front Headlamp aim too low both (4.1.2 (a))

MOT #14	2021-04-12 16:49
MOT test number	506465616078
Result	✗ Failed
MAJOR	Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
MAJOR	Front Headlamp aim too low both (4.1.2 (a))
MAJOR	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #13	2019-12-02 09:14
MOT test number	525842545413
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12	2018-12-06 13:46
MOT test number	610048011634
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11** 2018-12-06 11:55**MOT test number** 896904535494**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #10** 2017-11-28 15:36**MOT test number** 814114098381**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #9** 2016-09-29 12:06**MOT test number** 695148954667**Result** ✓ Passed**Advice** Nearside Rear Tyrewall slight worn**MOT #8** 2016-09-29 12:06**MOT test number** 501351766686**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Tyrewall slight worn**MOT #7** 2015-06-09 14:54**MOT test number** 285770765474**Result** ✓ Passed



MOT #6	2015-06-05 12:09
---------------	------------------

MOT test number	758076255100
------------------------	--------------

Result	✗ Failed
---------------	----------

Advice	Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
---------------	--

Fail	Front brake excessively fluctuating (3.7.B.3)
-------------	---

MOT #5	2014-06-25 09:30
---------------	------------------

MOT test number	809156974137
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2013-05-11 12:02
---------------	------------------

MOT test number	337771333137
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2012-05-17 19:53
---------------	------------------

MOT test number	285758532111
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2011-08-25 09:25
---------------	------------------

MOT test number	127617031222
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2010-09-01 19:33
---------------	------------------

MOT test number	771484540266
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
27 July 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-09-12
Last registration	2023-07-25
Complete history	See info



Registration #1	2007-09-12	8 mi
Registration #2	2010-09-01	44.573 mi
Registration #3	2011-08-25	49.298 mi
Registration #4	2012-05-17	51.374 mi
Registration #5	2013-05-11	68.884 mi
Registration #6	2014-06-25	82.221 mi
Registration #7	2015-06-05	87.929 mi
Registration #8	2015-06-09	88.000 mi
Registration #9	2016-09-29	98.360 mi
Registration #10	2016-09-29	98.360 mi
Registration #11	2017-11-28	109.114 mi
Registration #12	2018-01-01	110.000 mi
Registration #13	2018-01-01	110.000 mi
Registration #14	2018-01-01	110.000 mi
Registration #15	2018-01-01	110.000 mi
Registration #16	2018-01-01	110.000 mi
Registration #17	2018-01-01	110.000 mi
Registration #18	2018-01-01	110.000 mi
Registration #19	2018-01-01	110.000 mi
Registration #20	2018-01-01	110.000 mi
Registration #21	2018-01-01	110.000 mi
Registration #22	2018-01-01	110.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	130531