





report date: 2024-03-29

General information

Make	FORD
Model	FUSION ZETEC TDCI
Colour	Blue
Year of manufacture	2009
Top speed	98 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 2.000 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2022-04-01

Pictures 21

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2025-04-14
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #16	2024-04-14 13:30
MOT test number	716922171497
Result	✓ Passed
Next expiry date	2025-04-14
Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #15		2023-04-15 11:45
MOT test no	umber	258404992607
Result		✓ Passed
	Nearside Rear Child Seat fitted not allowing full inspection of adult belt Sub-frame ball joint has slight play both sides , lower outer (5.3.4 (a) (i))	

MOT #14	2022-04-08 09:3
MOT test	number 350882357802
Result	✓ Passed
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13		2021-08-17 10:02
MOT test	number	969278250611
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #12	2020-08-12 10:31
MOT test number	191779993904
Result	✓ Passed
MOT #11	2019-08-15 12:05
MOT test number	387255016504
Result	✓ Passed
MOT #10	2018-07-25 09:58
MOT test number	826518467548
Result	✓ Passed
MOT #9	2017-08-09 11:07
MOT test number	995025569345
Result	✓ Passed
MOT #8	2016-08-10 10:22
MOT test number	105539336322
Result	✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #7	2015-08-10 12:47
MOT test number	259512925293
Result	✓ Passed
Notice Both rear tyres cracking with age	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice Nearside front tyre cracking with age	

MOT #6	2015-08-10 12:47
MOT test number	216492825272
Result	X Failed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice Both rear tyres cracking with age	
Pass with rectification Nearside Headlamp aim too low (1.8)	
Notice Nearside front tyre cracking with age	

MOT #5	2014-08-04 09:36
MOT test number	687126514253
Result	✓ Passed
MOT #4	2013-07-29 09:56
MOT test number	418730013278
Result	✓ Passed
MOT #3	2012-08-22 09:47
MOT test number	406165432210
Result	√ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2	2012-07-09 15:24
MOT test number	907581992170
Result	✓ Passed
MOT #1	2012-03-24 10:12
MOT test number	245784182027
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	14 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report		e?

	More info >	
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-04-21
Last registration	2024-04-14
Complete history	See info



Registration #1	2009-04-21	6 mi
Registration #2	2012-03-24	23.317 mi
Registration #3	2012-07-09	26.790 mi
Registration #4	2012-08-22	26.796 mi
Registration #5	2013-07-29	30.182 mi
Registration #6	2014-08-04	33.575 mi
Registration #7	2015-08-10	35.886 mi
Registration #8	2016-08-10	38.464 mi
Registration #9	2017-08-09	40.312 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.70 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1162 kg
Max. allowed weight	1640 kg

Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	5	
Number of axles CarCheck.co.uk	2 page 13	3/13