





report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO DYNAMIQUE S NAV DCI
Colour	White
Year of manufacture	2017
Top speed	112 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	80.7 mpg
Consumption extra urban	91.1 mpg
Consumption combined	85.6 mpg
CO2 emission	85 g/km
CO2 label	A



CarCheck.co.uk page 1/11



Internet history

Entry 1


Date 2021-03-03

Pictures 8

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-06-13
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	10
Total items failed	5

MOT #6		2023-06-14 10:29
MOT test	number	717654027492
Result		✓ Passed
Next expi	ry date	2024-06-13
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	())
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5			2023-06-14 10:29
MOT test	number		460582816763
Result			X Failed
Pass wit	h rectification	Tyre pressure monitoring system	malfunctioning or obviously inoperative (5.2.3
Advice	Front Brake disc	worn, pitted or scored, but not ser	iously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyr	e slightly damaged/cracking or per	ishing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



GJ67ZZH

report date: 2024-03-28

MOT #4 2023-06-05 10:07 728141103188 **MOT test number** Result × Failed **Advice** Damage to offside front door Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) Fail Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Service light on Fail Windscreen in an unacceptable condition (3.2 (c) (i)) Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3		2022-06-08 10:27
MOT test	number	293173507043
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2	2021-06-07 14:55
MOT test number	845062791651
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #1	2020-10-15 08:05
MOT test number	114179593929
Result	✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	13 June 2024
Full MOT history	See MOT history

Tax calculation

1 10 10 10 1	
Vehicle class	49
Band	D
First licence fee (12 months)	£ 130,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



GJ67ZZH

report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Ov			L		4	
UN	wn	<u> </u>	n	9		rv

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

manus .	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-10-26
Last registration	2023-06-14
Complete history	See info



Registration #1	2017-10-26	14 mi
Registration #2	2020-10-15	59.894 mi
Registration #3		11.777 es
Registration #4	2021-06-07	60.828 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditionin
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1732 mm
Height	1448 mm
Length	4063 mm
Wheel base	2589 mm
Kerb weight	1090 kg
Max. allowed weight	1695 kg

Additional information

Fuel tank capacity	45 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	11/11

Number of axles2Engine numberR181078