



report date: 2024-03-29

## General information

Make	NISSAN
Model	PULSAR N-TEC DCI
Colour	Black
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	108 BHP
Max. torque	260 Nm at 2.500 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	68.9 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A





Internet history

Entry 2

Date	2021-09-22
Pictures	0
Listing price	<a href="#">View report</a>

source: [heycar.co.uk](#)

Entry 1

Date	2021-09-18
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-05
MOT pass rate	55 %
MOT passed	6
Failed MOT tests	5
Total advice items	22
Total items failed	7

MOT #11	2023-10-06 14:52
MOT test number	533670859512
Result	✓ Passed
Next expiry date	2024-10-05
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2023-10-04 07:50
MOT test number	663361024489
Result	✗ Failed
Fail	Offside Parking brake inoperative on one side (1.4.1 (a))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2022-09-30 13:45**MOT test number** 639350282440**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear handbrake slow in coming on requires adjustment**MOT #8** 2022-09-22 15:40**MOT test number** 258847315869**Result** ✗ Failed**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Offside Rear handbrake slow in coming on requires adjustment**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Rear heat shield insecure**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #7** 2021-10-05 13:47**MOT test number** 460826673127**Result** ✓ Passed**MOT #6** 2020-11-25 12:29**MOT test number** 165847967450**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.5mm 205/50/17 93y xl (5.2.3 (e))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #5** 2020-11-25 12:29**MOT test number** 649048924929**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.5mm 205/50/17 93y xl (5.2.3 (e))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**MOT #4** 2019-11-13 12:01**MOT test number** 453492897968**Result** ✓ Passed**MOT #3** 2019-11-13 12:01**MOT test number** 534270680090**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #2** 2018-11-19 16:52**MOT test number** 832693084988**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm worn on outer edge Yokohama 205/50/17 93Y (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm worn on outer edge Yokohama 205/50/17 93Y (5.2.3 (e))



MOT #12018-11-19 14:34

MOT test number986205810283

Result		✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3mm worn on outer edge Yokohama 205/50/17 93Y (5.2.3 (e))	
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm worn on outer edge Yokohama 205/50/17 93Y (5.2.3 (e))	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
5 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	5 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-11-27
Last registration	2023-10-06
Complete history	<a href="#">See info</a>



Registration #1	2015-11-27	23 mi
Registration #2	2018-11-19	42.195 mi
Registration #3	2018-11-19	42.196 mi
Registration #4	2019-11-13	50.810 mi
Registration #5	2019-11-13	50.810 mi
Registration #6	2020-11-25	58.971 mi
Registration #7	2020-11-25	58.971 mi
Registration #8	2020-11-25	58.971 mi
Registration #9	2020-11-25	58.971 mi
Registration #10	2020-11-25	58.971 mi
Registration #11	2020-11-25	58.971 mi
Registration #12	2020-11-25	58.971 mi
Registration #13	2020-11-25	58.971 mi
Registration #14	2020-11-25	58.971 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	81%
Pedestrian	75%
Safety systems	68%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2017 mm
Height	1520 mm
Length	4387 mm
Wheel base	2700 mm
Kerb weight	1352 kg
Max. allowed weight	1785 kg

Additional information

Fuel tank capacity	46 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	484730D
---------------	---------