



report date: 2024-03-29

General information

|                     |                |
|---------------------|----------------|
| Make                | CITROEN        |
| Model               | DS5 HDI DSTYLE |
| Colour              | Grey           |
| Year of manufacture | 2012           |
| Top speed           | 134 mph        |
| 0 - 60 mph          | 8.5 seconds    |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 161 BHP             |
| Max. torque             | 340 Nm at 2.000 rpm |
| Engine capacity         | 1.997 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 44.8 mpg            |
| Consumption extra urban | 68.9 mpg            |
| Consumption combined    | 57.7 mpg            |
| CO2 emission            | 133 g/km            |
| CO2 label               | E                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-01-29                  |
| Pictures      | 0                           |
| Listing price | <a href="#">View report</a> |

source: [autoonline.co.uk](#)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-06-08 |
| MOT pass rate      | 64 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 5          |
| Total advice items | 32         |
| Total items failed | 1          |

|                  |                  |
|------------------|------------------|
| MOT #14          | 2023-05-25 09:36 |
| MOT test number  | 455971324833     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-06-08       |

|                 |                  |
|-----------------|------------------|
| MOT #13         | 2022-06-09 07:48 |
| MOT test number | 256170365690     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #12         | 2022-05-05 08:20 |
| MOT test number | 607041011291     |
| Result          | ✗ Failed         |

**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

**MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))

**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #11** 2021-04-30 14:20**MOT test number** 976591738249**Result** ✓ Passed**Advice** Engine and under covers fitted obscuring some components**MOT #10** 2020-10-27 07:49**MOT test number** 426164942628**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt x 2**Advice** Oil leak**MOT #9** 2020-10-26 09:03**MOT test number** 317154411867**Result** ✗ Failed**Advice** Brake disc worn, but not excessively front lipped (1.1.14 (a) (i))**Advice** Oil leak**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Child Seat fitted not allowing full inspection of adult belt x 2**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #8** 2019-10-30 16:34**MOT test number** 294588258605**Result** ✓ Passed

**MOT #7** 2019-10-23 14:34**MOT test number** 870748799911**Result** ✗ Failed**MAJOR** Offside Side repeater with a multiple light source more than 1/2 not functioning (4.4.1 (a) (ii))**DANGEROUS** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #6** 2018-10-24 11:26**MOT test number** 202343753524**Result** ✓ Passed**Advice** Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Engine covers and under tray fitted**MOT #5** 2018-10-24 10:39**MOT test number** 224422699154**Result** ✗ Failed**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Engine covers and under tray fitted**Advice** Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #4** 2017-10-24 11:00**MOT test number** 444040468253**Result** ✓ Passed**Advice** Engine covers and under trays

**MOT #3** 2017-10-24 11:00**MOT test number** 315818286790**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Engine covers and under trays**MOT #2** 2016-10-29 13:34**MOT test number** 570296934375**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Engine covers and under trays fitted at time of test**MOT #1** 2015-10-31 12:42**MOT test number** 906428598461**Result** ✓ Passed**Advice** Under trays and engine trays fitted at time of test**Advice** Child seat fitted



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
8 June 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 July              |
| <b>Days left</b>        | 62                              |
| <b>MOT expiry date</b>  | 8 June 2024                     |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | E          |
| <b>Single payment (12 months)</b>              | £ 180,00,- |
| <b>Single six month payment</b>                | £ 99,00,-  |
| <b>Total payable by 12 monthly instalments</b> | £ 189,00,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 10,000 |
| Auction value               | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

|                      |               |
|----------------------|---------------|
| Number of plates     | 1             |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-03-29    |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-03-29    |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 16                       |
| First mileage registration | 2012-09-25               |
| Last registration          | 2023-05-25               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2012-09-25 | 29 mi     |
| Registration #2  | 2015-10-31 | 37.561 mi |
| Registration #3  | 2016-10-29 | 50.704 mi |
| Registration #4  | 2017-10-24 | 59.805 mi |
| Registration #5  | 2017-10-24 | 59.805 mi |
| Registration #6  | 2018-10-24 | 69.824 mi |
| Registration #7  | 2018-10-24 | 69.824 mi |
| Registration #8  | 2019-10-23 | 81.170 mi |
| Registration #9  | 2019-10-23 | 81.170 mi |
| Registration #10 | 2019-10-23 | 81.170 mi |
| Registration #11 | 2019-10-23 | 81.170 mi |
| Registration #12 | 2019-10-23 | 81.170 mi |
| Registration #13 | 2019-10-23 | 81.170 mi |
| Registration #14 | 2019-10-23 | 81.170 mi |
| Registration #15 | 2019-10-23 | 81.170 mi |
| Registration #16 | 2019-10-23 | 81.170 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 89%                             |
| Children       | 83%                             |
| Pedestrian     | 40%                             |
| Safety systems | 97%                             |
| Overall rating | 79%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1850 mm |
| Height              | 1508 mm |
| Length              | 4530 mm |
| Wheel base          | 2727 mm |
| Kerb weight         | 1540 kg |
| Max. allowed weight | 2130 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 60 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | DYZE4032519      |