



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX20 CRDI STYLE BLUE DRIVE
Colour	Grey
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	64.2 mpg
CO2 emission	117 g/km
CO2 label	C






Internet history

Entry 2


Date	2021-11-06
Pictures	56
Listing price	View report



source: [yesauto.com](#)

Entry 1

Date	2021-11-04
Pictures	32
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-07-27
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	20
Total items failed	1

MOT #7	2023-07-08 05:08
MOT test number	224728962664
Result	✓ Passed
Next expiry date	2024-07-27
Advice	Nearside Front Tyre slightly damaged inner wall (5.2.3 (d) (ii))

MOT #6	2023-07-08 05:08
MOT test number	493982879735
Result	✗ Failed
Advice	Nearside Front Tyre slightly damaged inner wall (5.2.3 (d) (ii))
Pass with rectification	Front Windscreen washer not working (3.5 (a))

MOT #5	2022-07-14 11:51
MOT test number	962148464994
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4**

2021-07-10 09:04

MOT test number

646781768388

Result

✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing inner and outer edge perishing and wearing (5.2.3 (d) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Brake disc worn, pitted or scored, but not seriously weakened both rear sides (1.1.14 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing inner edge perishing (5.2.3 (d) (ii))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #3

2020-07-14 16:20

MOT test number

578654881741

Result

✓ Passed

Advice Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Offside Front Wiper smearing

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Front Tyre wearing on inner edge

Advice Offside Rear Tyre slightly damaged/cracking or perishing In tread, also has a slight bulge (5.2.3 (d) (ii))



MOT #2	2019-07-18 15:06
MOT test number	799648570243
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Offside Windscreen wiper blade defective (3.4 (b) (i))

MOT #1	2018-07-28 14:44
MOT test number	867678139218
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
27 July 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-07-10
Last registration	2023-07-08
Complete history	See info



Registration #1	2015-07-10	17 mi
Registration #2	2018-07-28	34.447 mi
Registration #3	2019-07-18	43.054 mi
Registration #4	2020-07-14	47.601 mi
Registration #5	2021-07-10	48.910 mi
Registration #6	2022-07-20	50.227 mi
Registration #7	2023-07-08	51.544 mi
Registration #8	2024-07-15	52.861 mi
Registration #9	2025-07-22	54.178 mi
Registration #10	2026-07-29	55.495 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1370 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBEZ604522