



Mercedes-Benz



JRD459


report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | MERCEDES |
| Model | ML ML 270 CDI |
| Colour | Blue |
| Year of manufacture | 2005 |
| Top speed | 114 mph |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 163 BHP |
| Max. torque | 370 Nm at 1.600 rpm |
| Engine capacity | 2.688 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 22.8 mpg |
| Consumption extra urban | 35.3 mpg |
| Consumption combined | 29.7 mpg |
| CO2 emission | 241 g/km |
| CO2 label | L |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-06 |
| Pictures | 3 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2025-03-27 |
| MOT pass rate | 74 % |
| MOT passed | 17 |
| Failed MOT tests | 6 |
| Total advice items | 46 |
| Total items failed | 18 |

MOT #23 2024-03-14 09:52**MOT test number** 324979670195**Result** Passed**Next expiry date** 2025-03-27

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #22 2023-03-21 12:23**MOT test number** 411815692661**Result** Passed

- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #21 2022-03-28 14:01**MOT test number** 202849649301**Result** Passed

**MOT #20**

2021-03-02 15:57

MOT test number

200774368436

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #19

2021-02-19 11:06

MOT test number

193321506181

Result

✗ Failed

- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Brake pipe excessively corroded to offside rear (1.1.11 (c))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #18**

2020-02-25 08:39

MOT test number

806412935307

Result

✓ Passed

- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #17

2020-02-18 10:32

MOT test number

261568091909

Result

✗ Failed

- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #16**

2019-03-04 09:40

MOT test number

240621097430

Result

✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #15**

2019-02-28 08:24

MOT test number

753084474264

Result

✗ Failed

Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Front Outer Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**Fail** Rear Parking brake lever inoperative (1.1.6 (d))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #14**

2018-02-13 11:59

MOT test number

830193831808

Result

✓ Passed

Advice Rear Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Oil leak**Advice** Nearside Rear coil spring corroded (2.4.C.1b)

**MOT #13** 2017-02-28 14:55**MOT test number** 557096946445**Result** ✓ Passed**Advice** Beam intensity [both dip]**MOT #12** 2017-02-28 10:23**MOT test number** 154888877714**Result** ✗ Failed**Fail** Front position lamp(s) not working (1.1.A.3b)**Fail** Stop lamp not working centre (1.2.1b)**Advice** Beam intensity [both dip]**MOT #11** 2016-02-29 09:29**MOT test number** 178936907419**Result** ✓ Passed**MOT #10** 2015-02-25 13:17**MOT test number** 387376455011**Result** ✓ Passed**MOT #9** 2015-02-25 09:31**MOT test number** 738246355083**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Rear Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #8** 2014-02-26 09:21**MOT test number** 259527254070**Result** ✓ Passed**MOT #7** 2013-02-26 14:48**MOT test number** 157937653448**Result** ✓ Passed**Notice** Rear tyres perished**Notice** Slight play in both front inner tie rod ends**MOT #6** 2013-02-26 12:29**MOT test number** 237337753033**Result** ✗ Failed**Notice** Slight play in both front inner tie rod ends**Fail** Nearside Rear Anti-roll bar linkage missing (2.4.G.1)**Notice** Rear tyres perished**MOT #5** 2012-03-05 09:57**MOT test number** 156235162430**Result** ✓ Passed**MOT #4** 2011-03-04 15:09**MOT test number** 196073361415**Result** ✓ Passed

**MOT #3** 2010-06-05 09:50**MOT test number** 110646250164**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** N/s/f wiper blade split**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-05-26 12:55**MOT test number** 290836749109**Result** ✓ Passed**Advice** Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #1** 2008-05-13 14:11**MOT test number** 820074338144**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
27 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 1 |
| MOT expiry date | 27 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

| | |
|----------------------|---|
| Number of plates | 7 |
| Current registration |  ***** |
| Plate since | 2023-03-29 |
| Current registration |  ***** |
| Plate since | 2023-03-29 |

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 25 |
| First mileage registration | 2005-06-07 |
| Last registration | 2024-03-14 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2005-06-07 | 22 mi |
| Registration #2 | 2008-05-13 | 28.340 mi |
| Registration #3 | 2009-05-26 | 35.554 mi |
| Registration #4 | 2010-06-05 | 45.544 mi |
| Registration #5 | 2011-03-04 | 52.352 mi |
| Registration #6 | 2012-03-05 | 59.641 mi |
| Registration #7 | 2013-02-26 | 64.113 mi |
| Registration #8 | 2013-02-26 | 64.113 mi |
| Registration #9 | 2014-02-26 | 68.224 mi |
| Registration #10 | 2015-02-25 | 70.285 mi |
| Registration #11 | 2015-02-25 | 70.285 mi |
| Registration #12 | 2016-02-29 | 73.649 mi |
| Registration #13 | 2017-02-28 | 78.141 mi |
| Registration #14 | 2018-02-28 | 82.633 mi |
| Registration #15 | 2018-02-28 | 82.633 mi |
| Registration #16 | 2019-02-28 | 87.125 mi |
| Registration #17 | 2019-02-28 | 87.125 mi |
| Registration #18 | 2020-02-28 | 91.617 mi |
| Registration #19 | 2020-02-28 | 91.617 mi |
| Registration #20 | 2021-02-28 | 96.109 mi |
| Registration #21 | 2021-02-28 | 96.109 mi |
| Registration #22 | 2022-02-28 | 100.601 mi |
| Registration #23 | 2022-02-28 | 100.601 mi |
| Registration #24 | 2023-02-28 | 105.093 mi |
| Registration #25 | 2024-03-14 | 109.585 mi |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1833 mm |
| Height | 1820 mm |
| Length | 4638 mm |
| Wheel base | 2820 mm |
| Kerb weight | 2115 kg |
| Max. allowed weight | 2870 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 83 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 61296330309015 |