



report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 16V SX MAXI MULTIJET II
Colour	Silver
Year of manufacture	2017
Top speed	102 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	135 g/km
CO2 label	E





## MOT history

MOT expiry date	2024-04-17
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	15
Total items failed	3

MOT #7	2024-04-27 11:14
MOT test number	902604810981
Result	✓ Passed
Next expiry date	2025-04-26
Minor	Power steering fluid level below minimum (2.1.5 (b) (i))
Minor	Offside Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #6	2024-04-27 11:14
MOT test number	758133619096
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Minor	Power steering fluid level below minimum (2.1.5 (b) (i))
Minor	Offside Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #5** 2023-04-18 16:13**MOT test number** 371022139657**Result** ✓ Passed**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Oil leak, but not excessive (8.4.1 (a) (i))**MOT #4** 2023-04-01 13:37**MOT test number** 865818831446**Result** ✗ Failed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Nail in tyre**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**MOT #3** 2022-03-02 10:24**MOT test number** 207278677215**Result** ✓ Passed**Advice** Rear exhaust silencer corroded**MOT #2** 2021-03-06 10:46**MOT test number** 123961563794**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))



MOT #1	2020-08-20 10:59
MOT test number	426835522719
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 September 2024

✗  
**MOT**  
  
Expired:  
17 April 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	17 April 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-01
Last registration	2024-04-27
Complete history	<a href="#">See info</a>



Registration #1	2017-09-01	9 mi
Registration #2	2020-08-20	24.803 mi
Registration #3	2021-03-06	27.223 mi
Registration #4	2022-03-02	34.117 mi
Registration #5	2023-03-02	35.277 mi
Registration #6	2023-03-02	35.277 mi
Registration #7	2023-03-02	35.277 mi
Registration #8	2024-04-27	35.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	75%
Children	46%
Pedestrian	57%
Safety systems	25%
Overall rating	56%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1832 mm
Height	1880 mm
Length	4756 mm
Wheel base	3105 mm
Kerb weight	1365 kg
Max. allowed weight	2370 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2

Engine number 8092252