





General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Silver
Year of manufacture	-
Top speed	145 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	299 Nm at 4.100 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	26.4 mpg



Internet history

Entry 1	
Date	2021-10-02
Pictures	14
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #21	2021-10-05 10:10
MOT test number	843854737694
Result	✓ Passed
Next expiry date	2022-10-04

MOT #20		2020-09-18 13:51
MOT test	number	784833193925
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #19	2020-09-12 08:15
MOT test number	188648873940
Result	🗙 Failed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Electronic parking brake control defective so that it cannot be satisfactorily operation	ated (1.1.6 (d))
Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
FailBrake performance not tested (1.2.1 (g))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #18		2019-09-13 13:24
MOT test	number	957160671710
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #17	2019-09-09 09:17
MOT test number	198825729081
Result	🗙 Failed
Fail (b) (ii))Offside Rear Upper Suspension arm ball joint dust cover no longer prevents the in	ngress of dirt (5.3.4
Fail Offside Rear Drive shaft joint constant velocity boot split or insecure, no longer p of dirt (6.1.7 (g) (ii))	revents the ingress
Fail Front Lower Oil leaking excessively from engine (8.4.1 (a) (i))	
Fail (b) (ii))Offside Rear Lower Suspension arm ball joint dust cover no longer prevents the in	ngress of dirt (5.3.4
Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.3	1.2 (b))
MOT #16	2018-09-11 10:54

MOT test	number	623680085518
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Plastic engine,sills & under trays fitted	
Advice hub (5.3.4	Offside Rear Lower Suspension arm pin or bush worn but not resulting in (a) (i))	excessive movement on
Advice	Under side waxoiled	
Advice on hub (5.	Nearside Rear Lower Suspension arm pin or bush worn but not resulting in 3.4 (a) (i))	n excessive movement





MOT #15		2017-10-24 11:47
MOT test	number	414275106439
Result		✓ Passed
Advice	Nearside Rear Lower Suspension arm has slight play in a pin/bearing (2.4.G.2)	
Advice	Undertrays & plastic sills fitted obscuring view	
Advice	Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)	
Advice	Oil leak	
Advice	Offside Rear Lower Suspension arm has slight play in a pin/bearing (2.4.G.2)	
Advice	Front tyres worn low on inner edges	

MOT #14	2017-10-20 09:46
MOT test number	248327820156
Result	🗙 Failed
Advice Undertrays & plastic sills fitted obscuring view	
Fail Nearside Rear Tie bar/rod ball joint dust cover excessively deteriorated so that it no the ingress of dirt (2.4.G.2)	o longer prevents
Advice Nearside Rear Lower Suspension arm has slight play in a pin/bearing (2.4.G.2)	
Fail Nearside Front Lower Shock absorber has an excessively worn bush (2.7.4)	
Advice Oil leak	
Advice Front tyres worn low on inner edges	
Fail Offside Rear Tie bar/rod ball joint dust cover excessively deteriorated so that it no l the ingress of dirt (2.4.G.2)	longer prevents
Advice Offside Rear Lower Suspension arm has slight play in a pin/bearing (2.4.G.2)	
Advice Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)	

MOT #13	2016-08-26 13:25
MOT test number	495944668603
Result	✓ Passed





MOT #12		2015-10-30 15:42
MOT test	number	300176756410
Result		✓ Passed
Advice	Oil leak	
Advice	Child seats fitted no allowing full inspection of adult seat belts	
Advice	Under trays fitted not allowing full inspection of some underside components	

MOT #11 2015-10-30 12:13 **MOT test number** 324178725603 Result × Failed Advice Child seats fitted no allowing full inspection of adult seat belts Advice Under trays fitted not allowing full inspection of some underside components Offside Front Headlamp aim too low (1.8) Fail Advice Oil leak Fail Nearside Front Headlamp aim too low (1.8) Fail Nearside Rear Anti-roll bar linkage insecure broken (2.4.G.1)

MOT #10	2014-10-20	0 11:21
MOT test	number 2787133	394291
Result	✓ ×	Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	





MOT #9		2013-10-28 15:48
MOT test	number	116541503316
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	O/s/f wiper blade torn but still clear the screen	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	N/s/f wiper blade torn but still clears the screen	

MOT #8	2012-10-29 16:27
MOT test number	605513102324
Result	✓ Passed

MOT #7		2012-10-29 14:42
MOT test number		407113602471
Result		🗙 Failed
Fail Nearside Headlam	np aim too low (1.8)	
Fail Offside Headlamp	aim too low (1.8)	

MOT #6	2011-10-24 14:41
MOT test number	665327791213
Result	✓ Passed
Notice Front tyres worn on inner edges	

MOT #5	2010-09-30 10:43
MOT test number	471013070256
Result	✓ Passed





MOT #4			2009-09-29 11:46
MOT test	number		163142179255
Result			✓ Passed
MOT #3			2008-09-24 16:58
MOT test	number		691048468282
Result			✓ Passed
MOT #2			2007-09-12 15:12
MOT test	number		413135657274
Result			🗙 Failed
Notice	Front brake pads	low	
Pass wit	th rectification	Offside Headlamp aim too low (1.8)	
Advice	Offside Rear Tyre	e worn close to the legal limit (4.1.E.1)	
Notice	Various small sto	nechips in swept area of windscreen	
Pass wit	th rectification	Nearside Headlamp aim too low (1.8)	
Notice	Various suspensi	on bushes starting to perish	
Advice	Nearside Rear Ty	re worn close to the legal limit (4.1.E.1)	

MOT #1		2007-09-12 15:12
MOT test	number	272375257259
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Front brake pads low	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Various small stonechips in swept area of windscreen	
Notice	Various suspension bushes starting to perish	





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and a second s	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-09-29
Last registration	2021-10-05
Complete history	<u>See info</u>



Registration #1	2004-09-29	6 mi
Registration #2	2007-09-12	27.536 mi
Registration #3	2008-09-24	33.468 mi
Registration #4	2009-09-29	36.397 mi
Registration #5	2010-09-30	39.707 mi
Registration #6	2011-10-24	44.145 mi
Registration #7	2012-10-29	44.869 mi
Registration #8	2012-10-29	44.870 mi
Registration #9	2013-10-28	49.873 mi
Registration #10	2014-10-20	57.377 mi
Registration #11	2015-10-30	64.266 mi
Registration #12		11.777 esi
Registration #13		11.117 est
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.117 est
Registration #17		11.777 esi
Registration #18		11.777 esi
Registration #19		11.117 esi
Registration #20		11.117 est
Registration #21		11.117 esi
Registration #22		11.117 esi





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1710 kg
Max. allowed weight	2180 kg
Additional information	
Additional information Fuel tank capacity	69 I
	69 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 4