



General information

Make	VOLVO
Model	V70 D3 SE
Colour	Black
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	54.3 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-12
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2024-10-31
<b>MOT pass rate</b>	85 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	12
<b>Total items failed</b>	5

<b>MOT #13</b>	2023-11-01 08:54
<b>MOT test number</b>	148012940289
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-10-31

<b>MOT #12</b>	2022-10-06 11:37
<b>MOT test number</b>	329595678956
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #11</b>	2021-10-27 11:25
<b>MOT test number</b>	585768417768
<b>Result</b>	✓ Passed

**MOT #10** 2021-10-22 13:06**MOT test number** 329871436933**Result** ✗ Failed

- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Minor** Offside Front Brake hose slightly twisted (1.1.12 (b) (ii))

**MOT #9** 2021-02-26 11:53**MOT test number** 788289198509**Result** ✓ Passed**MOT #8** 2020-03-04 18:02**MOT test number** 357280200973**Result** ✓ Passed**MOT #7** 2020-03-04 17:01**MOT test number** 994369162003**Result** ✗ Failed

- Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #6** 2019-02-25 09:06**MOT test number** 209413976768**Result** ✓ Passed

**MOT #5** 2018-03-07 14:57**MOT test number** 457699620178**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2017-03-07 15:30**MOT test number** 776420340078**Result** ✓ Passed**MOT #3** 2016-03-02 16:52**MOT test number** 470277267101**Result** ✓ Passed**MOT #2** 2015-03-09 15:12**MOT test number** 769248565008**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #1** 2014-03-13 16:59**MOT test number** 499642574068**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
31 October 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	31 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-06-10
Last registration	2023-11-01
Complete history	<a href="#">See info</a>



Registration #1	2011-06-10	23 mi
Registration #2	2014-03-13	43.561 mi
Registration #3	2015-03-09	55.451 mi
Registration #4	2016-03-02	64.053 mi
Registration #5	2017-03-07	70.363 mi
Registration #6	2018-03-07	75.284 mi
Registration #7	2019-02-25	81.456 mi
Registration #8	2020-03-04	98.261 mi
Registration #9	2020-03-04	98.261 mi
Registration #10	2020-03-04	98.261 mi
Registration #11	2020-03-04	98.261 mi
Registration #12	2020-03-04	98.261 mi
Registration #13	2020-03-04	98.261 mi
Registration #14	2020-03-04	98.261 mi
Registration #15	2020-03-04	98.261 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1750 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1047548