



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO EASY
Colour	Grey
Year of manufacture	2013
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-02-13
Pictures	32
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-12
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	19
Total items failed	6

MOT #13	2024-01-09 14:42
MOT test number	469299242227
Result	✓ Passed
Next expiry date	2025-01-12
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Temporary fuel cap fitted

MOT #12	2023-01-13 14:20
MOT test number	684835876337
Result	✓ Passed

MOT #11	2022-04-25 15:27
MOT test number	779120341466
Result	✓ Passed

**MOT #10** 2022-04-21 11:42**MOT test number** 475614011072**Result** ✗ Failed**Advice** Exhaust corroded**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** N/s rear brake sticking slightly.**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge o/s and n/s (5.2.3 (e))**MOT #9** 2021-11-04 16:26**MOT test number** 798907093532**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2021-11-03 11:36**MOT test number** 100660039494**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2020-11-09 11:12**MOT test number** 200002947565**Result** ✓ Passed**Advice** Temporary fuel cap**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.8mm at lowest point (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively both inner face's (1.1.14 (a) (i))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #6** 2019-11-01 12:06**MOT test number** 362018596473**Result** ✓ Passed**Advice** Temporary fuel cap fitted**MOT #5** 2019-10-31 12:48**MOT test number** 372070800610**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Temporary fuel cap fitted**MOT #4** 2018-10-25 09:47**MOT test number** 427072131911**Result** ✓ Passed**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))



<b>MOT #3</b>	2018-10-25 09:47
---------------	------------------

<b>MOT test number</b>	568122854283
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Fuel cap/sealing device ineffective (6.1.3 (b) (i))
--------------------------------	---

<b>Minor</b>	Nearside Windscreen wiper blade defective (3.4 (b) (i))
--------------	---

<b>MOT #2</b>	2017-10-26 12:13
---------------	------------------

<b>MOT test number</b>	481183810398
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2016-09-12 10:36
---------------	------------------

<b>MOT test number</b>	464661470842
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
12 January 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	12 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>YX63HCH</b>
Plate since	2019-09-28
Current registration	<b>YX63HCH</b>
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-09-18
Last registration	2024-01-09
Complete history	<a href="#">See info</a>



Registration #1	2013-09-18	19 mi
Registration #2	2016-09-12	12.023 mi
Registration #3	2017-10-26	15.799 mi
Registration #4	2018-10-25	22.723 mi
Registration #5	2018-10-25	22.723 mi
Registration #6	2019-10-31	30.063 mi
Registration #7	2019-11-01	30.075 mi
Registration #8	2020-11-09	35.538 mi
Registration #9	2020-11-09	35.538 mi
Registration #10	2020-11-09	35.538 mi
Registration #11	2020-11-09	35.538 mi
Registration #12	2020-11-09	35.538 mi
Registration #13	2020-11-09	35.538 mi
Registration #14	2020-11-09	35.538 mi
Registration #15	2020-11-09	35.538 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	0272619