



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT SE TDI DSG 140
Colour	Silver
Year of manufacture	-
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #11</b>	2022-04-27 11:02
<b>MOT test number</b>	674750081343
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-04-26

<b>MOT #10</b>	2020-12-10 10:55
<b>MOT test number</b>	441881352101
<b>Result</b>	✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #9</b>	2019-06-13 11:43
<b>MOT test number</b>	310921868547
<b>Result</b>	✓ Passed

<b>MOT #8</b>	2018-07-02 08:38
<b>MOT test number</b>	424299900681
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2016-12-05 14:35
<b>MOT test number</b>	460798915898
<b>Result</b>	✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

<b>MOT #6</b>	2016-12-02 13:16
<b>MOT test number</b>	829938480489
<b>Result</b>	✗ Failed

**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #5** 2015-11-03 11:03**MOT test number** 539319560867**Result** ✓ Passed**Advice** Offside front tyre on legal limit on inner edge and has a nail in.**Advice** Nearside front tyre worn close to legal limit on inner edge.**MOT #4** 2014-05-23 14:28**MOT test number** 999543744169**Result** ✓ Passed**MOT #3** 2013-05-10 15:09**MOT test number** 408690433102**Result** ✓ Passed**MOT #2** 2013-05-10 15:09**MOT test number** 905820733124**Result** ✗ Failed**Pass with rectification** Offside Front Valve stem seriously misaligned (4.1.D.1e)**Pass with rectification** Offside Rear Valve stem seriously misaligned (4.1.D.1e)**Pass with rectification** Nearside Front Valve stem seriously misaligned (4.1.D.1e)**Pass with rectification** Nearside Rear Valve stem seriously misaligned (4.1.D.1e)**MOT #1** 2012-05-15 14:30**MOT test number** 385866332125**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>LS09ZJE</b>
Plate since	2024-03-29
Current registration	<b>LS09ZJE</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2009-05-30
Last registration	2022-04-27
Complete history	<a href="#">See info</a>



Registration #1	2009-05-30	8 mi
Registration #2	2012-05-15	16.154 mi
Registration #3	2013-05-10	20.134 mi
Registration #4	2014-05-23	21.399 mi
Registration #5	2015-11-03	69.511 mi
Registration #6	2016-12-02	111.410 mi
Registration #7	2017-05-22	121.277 mi
Registration #8	2017-05-22	121.277 mi
Registration #9	2017-05-22	121.277 mi
Registration #10	2017-05-22	121.277 mi
Registration #11	2017-05-22	121.277 mi

More info >





Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Engine number**

BKD C66894