



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA SRI CDTI 150
Colour	Silver
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	315 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	48.7 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-06-30
Pictures	34
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-07
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	14
Total items failed	9

MOT #20	2024-03-06 08:38
MOT test number	545804812337
Result	✓ Passed
Next expiry date	2025-03-07

MOT #19	2024-03-05 09:34
MOT test number	831756612706
Result	✗ Failed
Fail	Exhaust emissions likely to be affected by an exhaust leak exhaustb in half (8.2.1.1 (b))
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #18	2023-02-22 14:31
MOT test number	594396563123
Result	✓ Passed

MOT #17	2022-02-28 16:51
MOT test number	582281980690
Result	✓ Passed

**MOT #16** 2021-03-08 14:54**MOT test number** 730993800661**Result** ✓ Passed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #15** 2021-03-08 14:54**MOT test number** 295846813899**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #14** 2020-02-20 12:59**MOT test number** 840163485395**Result** ✓ Passed**MOT #13** 2019-08-21 14:22**MOT test number** 835539400144**Result** ✓ Passed**MOT #12** 2018-05-31 11:23**MOT test number** 699128352344**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #11** 2018-05-31 11:23**MOT test number** 288169314837**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #10** 2017-05-30 12:36**MOT test number** 907154600196**Result** ✓ Passed**Advice** Brake pipe slightly corroded front to rear (3.6.B.2c)**MOT #9** 2016-06-16 09:39**MOT test number** 163711439412**Result** ✓ Passed**MOT #8** 2016-06-16 08:46**MOT test number** 779429795366**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #7** 2015-06-18 12:01**MOT test number** 465869465131**Result** ✓ Passed

**MOT #6** 2015-06-18 09:24**MOT test number** 649099765137**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** O/S wiper blade split**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #5** 2014-06-20 13:19**MOT test number** 227131374479**Result** ✓ Passed**MOT #4** 2014-06-20 13:19**MOT test number** 587721674177**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #3** 2013-06-20 09:34**MOT test number** 149591373129**Result** ✓ Passed**Notice** Near side and offside rear tyres worn on outside edges.**MOT #2** 2012-06-13 09:45**MOT test number** 545475262123**Result** ✓ Passed**Notice** Nail in offside rear tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2011-05-23 11:22
MOT test number	376413841140
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
7 March 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	7 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-06-13
Last registration	2024-03-06
Complete history	See info



Registration #1	2008-06-13	18 mi
Registration #2	2011-05-23	31.669 mi
Registration #3	2012-06-13	38.344 mi
Registration #4	2013-06-20	43.411 mi
Registration #5	2014-06-20	49.977 mi
Registration #6	2015-06-18	55.934 mi
Registration #7	2015-06-18	55.934 mi
Registration #8	2016-06-16	61.125 mi
Registration #9	2016-06-16	61.125 mi
Registration #10	2017-05-30	66.297 mi
Registration #11	2018-05-31	75.815 mi
Registration #12	2019-05-31	85.333 mi
Registration #13	2020-05-31	94.851 mi
Registration #14	2021-05-31	104.369 mi
Registration #15	2022-05-31	113.887 mi
Registration #16	2023-05-31	123.405 mi
Registration #17	2024-03-06	132.923 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2033 mm
Height	1467 mm
Length	4249 mm
Wheel base	2614 mm
Kerb weight	1346 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	17287056