





report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Blue
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	129 Nm at 4.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2022-01-27

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT #18 2022-12-21 15:52

MOT test number 714861725377

Result ✓ Passed

Next expiry date 2023-12-20

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Front Lower Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17 2022-06-30 07:38

MOT test number 456113301037

Result \rightarrow Passed

Advice Nearside Inner Suspension component mounting prescribed area is corroded but not considered excessive and outer sill (5.3.6 (a) (i))

Advice Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Rear Sub-frame pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

Advice Offside Inner Suspension component mounting prescribed area is corroded but not considered excessive and outer sill (5.3.6 (a) (i))

Advice Rear Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))

Advice Headlamp has a product on the light source but not seriously reducing light output both (4.1.4 (b))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #16 2021-06-21 09:06

MOT test number 386428786967

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 3/12

Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))



report date: 2024-03-28

MOT #15	2020-06-19 08:53
MOT test number	156241471805
Result	✓ Passed
MOT #14	2019-06-24 15:29
MOT test number	394044311968
Result	✓ Passed
MOT #13	2019-06-24 10:45
MOT test number	365086585426
Result	× Failed
Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	

MOT #12	2018-06-18 13:22
MOT test number	777049501341
Result	✓ Passed
MOT #11	2018-06-18 07:20
MOT test number 388106804602	
Result	× Failed
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	

MOT #10	2017-07-03 11:05
MOT test number	229174973439
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #9	2017-07-03 09:11
MOT test number	555590270200
Result	× Failed
Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail Offside Windscreen washer provides insufficient washer liquid (8.2.3)	

MOT #8		2016-03-22 13:15
MOT test	number	955748705314
Result		✓ Passed
Advice	Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)	
Advice	Offside Brake pipe slightly corroded front to rear (3.6.B.2c)	

MOT #7	2015-04-07 10:50
MOT test number	506047895040
Result	✓ Passed
MOT #6	2015-04-06 11:48
MOT test number	968196795055
Result	X Failed
Fail Front brake application uneven (3.7.B.2)	

MOT #5	2014-04-02 15:11
MOT test number	917702694052
Result	✓ Passed
MOT #4	2013-03-28 10:43
MOT test number	879037983002
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT #3	2012-03-27 11:30
MOT test number	339647282071
Result	✓ Passed
MOT #2	2011-04-05 12:07
MOT test number	487985391000
Result	✓ Passed
MOT #1	2010-04-07 10:53
MOT test number	550507490081
Result	✓ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

SD56FSO

report date: 2024-03-28

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

factor scincol

See in this check if this TOYOTA had different number plates.

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-11-17
Last registration	2022-12-21
Complete history	See info



Registration #1	2006-11-17	15 mi
Registration #2	2010-04-07	3.309 mi
Registration #3	2011-04-05	3.672 mi
Registration #4	2012-03-27	3.795 mi
Registration #5	2013-03-28	4.072 mi
Registration #6	2014-04-02	5.275 mi
Registration #7	2015-04-06	7.894 mi
Registration #8	2015-04-07	7.896 mi
Registration #9	2016-03-22	9.998 mi
Registration #10	2017-07-03	17.957 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.777 es
Registration #16		11.777 es
Registration #17		9.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		n.m.

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number 4ZZU798028