



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI T3
Colour	Blue
Year of manufacture	2005
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1	
Date	2021-06-20
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2021-09-09
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	57
Total items failed	9

MOT #19	2020-09-04 09:18
MOT test number	652755169925
Result	✓ Passed
Next expiry date	2021-09-09
Advice	Front Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))
Advice	Rear axle carroded
Advice	Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Inner sills carroded

**MOT #18**

2020-09-01 09:50

MOT test number

995420053959

Result**✗ Failed**

- Advice** Rear axle corroded
- Advice** Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
- MAJOR** Front Headlamp aim projected beam image is obviously incorrect both (4.1.2 (c))
- Advice** Inner sills corroded
- Advice** Front Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))
- MAJOR** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner wing (5.3.6 (a) (i))

MOT #17

2019-08-20 10:17

MOT test number

323821654684

Result**✓ Passed**

- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #16

2019-08-20 08:58

MOT test number

616658302362

Result**✗ Failed**

- DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #15**

2018-09-10 12:55

MOT test number

323985445535

Result

✓ Passed

Advice

Under body sealed (black)

MOT #14

2018-09-05 15:50

MOT test number

336898939921

Result

✗ Failed

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Corrosion present on front suspension components

Advice

Corrosion present on floor various

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Corrosion present on front subframe

DANGEROUS

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Corrosion present on offside and nearside inner sills

Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13

2017-08-02 11:19

MOT test number

430699090462

Result

✓ Passed

Advice

Exhaust has a minor leak of exhaust gases (7.1.2)

Advice

Offside rear brake fluctuating, but not excessively (3.7.B.3)

Advice

Nearside rear brake fluctuating, but not excessively (3.7.B.3)

**MOT #12**

2017-07-28 15:12

MOT test number

723114963767

Result**✗ Failed****Advice** Nearside rear brake fluctuating, but not excessively (3.7.B.3)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside rear brake fluctuating, but not excessively (3.7.B.3)**Fail** Offside front brake binding (3.7.B.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #11**

2016-08-05 14:58

MOT test number

327359545911

Result**✓ Passed****Advice** Nearside Rear Brake pipe slightly corroded Front to back pipe at front, at distribution block under engine (3.6.B.2c)**Advice** Nearside Front Brake pipe slightly corroded Under bonnet - pipe from ABS pump, adjacent brake booster (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded Under bonnet - pipe from ABS pump, adjacent brake booster (3.6.B.2c)

**MOT #10**

2016-08-04 10:54

MOT test number

503464802835

Result**✗ Failed**

Advice Offside Rear Brake pipe slightly corroded Under bonnet - pipe from ABS pump, adjacent brake booster (3.6.B.2c)

Advice Offside Front Wheel binding slightly when rotated by hand

Fail Nearside Front front brake binding (3.7.B.1)

Advice Offside rear parking (secondary) brake grabbing slightly (3.7.B.6b)

Advice Nearside Rear Brake pipe slightly corroded Front to back pipe at front, at distribution block under engine (3.6.B.2c)

Advice Engine oil low on dipstick

Advice Nearside Front Brake pipe slightly corroded Under bonnet - pipe from ABS pump, adjacent brake booster (3.6.B.2c)

Fail Front Brakes imbalanced across an axle 43% Imbalance (3.7.B.5b)

Advice Nearside rear parking (secondary) brake grabbing slightly (3.7.B.6b)

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Wiper blade rubbers deteriorated

MOT #9

2015-07-31 15:22

MOT test number

236552615276

Result**✓ Passed**

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #8** 2015-07-30 13:04**MOT test number** 198451515203**Result** ✗ Failed**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Horn not working (1.6.2a)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Headlamp aim too low (1.8)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2014-07-23 15:56**MOT test number** 457054404218**Result** ✓ Passed**Notice** Additional high level stop light not working**Advice** Nearside Front Suspension arm corroded but not seriously weakened (2.4.G.1)**Notice** Nearside front driveshaft inner boot leaking lubricant**Advice** Offside Front Suspension arm corroded but not seriously weakened (2.4.G.1)**MOT #6** 2013-07-29 09:58**MOT test number** 588640713200**Result** ✓ Passed**Advice** Offside Front Suspension arm corroded but not seriously weakened (2.4.G.1)**Advice** Nearside Front Suspension arm corroded but not seriously weakened (2.4.G.1)



MOT #5	2012-08-06 12:57
---------------	------------------

MOT test number	867179012223
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #4	2011-08-08 08:46
---------------	------------------

MOT test number	828270121216
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2010-10-21 15:45
---------------	------------------

MOT test number	594364390214
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2009-10-30 10:52
---------------	------------------

MOT test number	621533009335
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2008-11-05 10:25
---------------	------------------

MOT test number	530850118388
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✕
Untaxed

Tax expired:
26 December 2020

✕
MOT

Expired:
9 September 2021

Tax status	Expired at 26 December 2020
Days left	1220 days too late
MOT expiry date	9 September 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-12-09
Last registration	2020-09-04
Complete history	See info



Registration #1	2005-12-09	8 mi
Registration #2	2008-11-05	25.228 mi
Registration #3	2009-10-30	33.994 mi
Registration #4	2010-10-21	43.971 mi
Registration #5	2011-08-08	47.508 mi
Registration #6	2012-08-06	54.988 mi
Registration #7	2013-07-29	63.780 mi
Registration #8	2014-07-23	72.890 mi
Registration #9	2015-07-30	80.832 mi
Registration #10	2015-07-31	80.834 mi
Registration #11	2016-08-04	85.308 mi
Registration #12	2016-08-04	85.308 mi
Registration #13	2016-08-04	85.308 mi
Registration #14	2016-08-04	85.308 mi
Registration #15	2016-08-04	85.308 mi
Registration #16	2016-08-04	85.308 mi
Registration #17	2016-08-04	85.308 mi
Registration #18	2016-08-04	85.308 mi
Registration #19	2016-08-04	85.308 mi
Registration #20	2016-08-04	85.308 mi
Registration #21	2016-08-04	85.308 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1215 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZU675172