



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Red
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-09-24
Pictures	46
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-11
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	10
Total items failed	15

MOT #12	2023-12-09 13:41
MOT test number	290640409488
Result	✓ Passed
Next expiry date	2024-12-11

MOT #11	2022-12-12 09:23
MOT test number	159615354788
Result	✓ Passed

**Advice** Engine covers and undertrays fitted obscuring some components

**MOT #10**

2022-12-08 12:59

**MOT test number**

816696199670

**Result****✗ Failed****Fail**

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice**

Spare tyre defective

**Fail**

Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Fail**

Offside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))

**Fail**

Parking brake efficiency below requirements (1.4.2 (a) (i))

**Fail**

Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice**

Engine covers and undertrays fitted obscuring some components

**Fail**

Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Fail**

Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Fail**

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail**

Service brake efficiency below requirements (1.2.2 (a) (i))

**Fail**

Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail**

Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #9**

2021-09-28 14:06

**MOT test number**

895640563688

**Result****✓ Passed****MOT #8**

2020-11-18 15:05

**MOT test number**

566452157955

**Result****✓ Passed**

**MOT #7** 2019-06-05 09:48**MOT test number** 468803385162**Result** ✓ Passed**MOT #6** 2018-03-20 11:56**MOT test number** 571950283592**Result** ✓ Passed**MOT #5** 2017-03-20 13:43**MOT test number** 699270560725**Result** ✓ Passed**MOT #4** 2017-03-20 11:21**MOT test number** 597297437128**Result** ✗ Failed**Advice** FRONT BRAKE DISCS POOR CONDITION**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** REAR BRAKE PADS LOW**MOT #3** 2016-09-26 16:07**MOT test number** 994660447322**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2016-09-26 11:22
MOT test number	421245801528
Result	✗ Failed
Fail	Nearside Rear Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Rear Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)

MOT #1	2015-11-16 16:45
MOT test number	577426086188
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
Advice	Front tyres worn on inner edges



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
11 December 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	11 December 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-10-10
Last registration	2023-12-09
Complete history	<a href="#">See info</a>



Registration #1	2012-10-10	12 mi
Registration #2	2015-11-16	31.270 mi
Registration #3	2016-09-26	41.244 mi
Registration #4	2016-09-26	41.244 mi
Registration #5	2017-03-20	44.321 mi
Registration #6	2017-03-20	44.321 mi
Registration #7	2018-03-20	56.835 mi
Registration #8	2019-03-20	69.349 mi
Registration #9	2019-03-20	69.349 mi
Registration #10	2019-03-20	69.349 mi
Registration #11	2019-03-20	69.349 mi
Registration #12	2019-03-20	69.349 mi
Registration #13	2019-03-20	69.349 mi
Registration #14	2019-03-20	69.349 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1880 mm
Height	1690 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	2001 kg
Max. allowed weight	2600 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number	D4HBCU692526
---------------	--------------