



report date: 2024-03-29

General information

| | |
|---------------------|-----------------------------------|
| Make | VOLKSWAGEN |
| Model | AMAROK DC V6 TDI AVENTURA 4MOTION |
| Colour | Black |
| Year of manufacture | 2017 |
| Top speed | 114 mph |
| 0 - 60 mph | 9.1 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 204 BHP |
| Max. torque | 500 Nm at 2.750 rpm |
| Engine capacity | 2.967 cc |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 32.8 mpg |
| Consumption extra urban | 38.7 mpg |
| Consumption combined | 36.2 mpg |
| CO2 emission | 203 g/km |
| CO2 label | K |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-30 |
| Pictures | 2 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-08 |
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 8 |
| Total items failed | 1 |

| | |
|------------------|--|
| MOT #5 | 2023-11-09 08:50 |
| MOT test number | 429770283587 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-08 |
| Advice | Front Inner Brake disc worn, but not excessively both sides (1.1.14 (a) (i)) |
| Advice | Offside Front Shock absorbers has light misting of oil (5.3.2 (b)) |
| Advice | Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) |
| Advice | Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

| | |
|-----------------|---|
| MOT #4 | 2022-10-13 12:39 |
| MOT test number | 531493780893 |
| Result | ✓ Passed |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

| | |
|-----------------|--|
| MOT #3 | 2021-10-15 14:02 |
| MOT test number | 883220909562 |
| Result | ✓ Passed |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |



| | |
|-----------------|--|
| MOT #2 | 2020-11-13 10:10 |
| MOT test number | 234696148977 |
| Result | ✓ Passed |
| Minor | Offside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i)) |

| | |
|-----------------|--|
| MOT #1 | 2020-11-12 11:15 |
| MOT test number | 650077039816 |
| Result | ✗ Failed |
| Fail | Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) |
| Minor | Offside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i)) |



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
8 November 2024

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 1 |
| MOT expiry date | 8 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---------------------------|------------|
| Vehicle class | 39 |
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 7 |
| First mileage registration | 2017-11-28 |
| Last registration | 2023-11-09 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2017-11-28 | 16 mi |
| Registration #2 | 2020-11-12 | 40.467 mi |
| Registration #3 | 2020-11-13 | 40.468 mi |
| Registration #4 | 2023-11-09 | 40.468 mi |
| Registration #5 | 2023-11-09 | 40.468 mi |
| Registration #6 | 2023-11-09 | 40.468 mi |
| Registration #7 | 2023-11-09 | 40.468 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 86% |
| Children | 64% |
| Pedestrian | 47% |
| Safety systems | 57% |
| Overall rating | 71% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2228 mm |
| Height | 1834 mm |
| Length | 5321 mm |
| Kerb weight | 2176 kg |
| Max. allowed weight | 3290 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 80 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

Engine number

DDXB021502