



report date: 2024-03-29

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS GRAND PICASSO
Colour	Grey
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg





Internet history

Entry 1

Date	2022-02-23
Pictures	30
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #16

2023-05-13 12:51

MOT test number

858032383895

Result

✗ Failed

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Front Windscreen washer not working (3.5 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))
- Fail** Emissions unable to be completed engine oil below minimum (8.2.2.2 (e))

MOT #15

2022-03-19 13:31

MOT test number

950916115258

Result

✓ Passed

- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #14** 2021-06-23 09:14**MOT test number** 151131125659**Result** ✓ Passed**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #13** 2021-06-23 09:14**MOT test number** 231658670828**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #12** 2020-06-16 11:02**MOT test number** 720302321877**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2019-06-27 15:02**MOT test number** 459620346414**Result** ✓ Passed**MOT #10** 2019-04-17 15:01**MOT test number** 925748289253**Result** ✓ Passed

**MOT #9** 2018-02-21 09:38**MOT test number** 240750920579**Result** ✓ Passed**Advice** Nearside rear outer seat base does not stay down**Advice** Oil leak**MOT #8** 2018-02-21 09:38**MOT test number** 944895556641**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside rear outer seat base does not stay down**Advice** Oil leak**MOT #7** 2017-02-23 09:38**MOT test number** 344605326629**Result** ✓ Passed**Advice** Both front tyres wearing inside edges and offside front slight damage to outer sidewall**Advice** Oil leak**Advice** Offside park brake lower effort**MOT #6** 2016-02-15 10:30**MOT test number** 560886817766**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front corroded (3.5.1i)**Advice** Offside park brake lower effort

**MOT #5** 2015-02-25 09:15**MOT test number** 136416955031**Result** ✓ Passed**MOT #4** 2014-02-05 08:52**MOT test number** 705716734091**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-02-27 13:38**MOT test number** 419188353095**Result** ✓ Passed**MOT #2** 2013-02-27 13:38**MOT test number** 628298953077**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2012-05-03 11:24**MOT test number** 117154022182**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	YR09ZZO
Plate since	2019-09-29
Current registration	YR09ZZO
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-04-30
Last registration	2023-05-13
Complete history	See info



Registration #1	2009-04-30	25 mi
Registration #2	2012-05-03	46.180 mi
Registration #3	2013-02-27	55.451 mi
Registration #4	2014-02-05	62.676 mi
Registration #5	2015-02-25	70.150 mi
Registration #6	2016-02-15	76.158 mi
Registration #7	2017-02-23	82.386 mi
Registration #8	2018-02-21	87.598 mi
Registration #9	2018-02-21	87.598 mi
Registration #10	2019-05-20	95.377 mi
Registration #11	2019-05-20	95.377 mi
Registration #12	2019-05-20	95.377 mi
Registration #13	2019-05-20	95.377 mi
Registration #14	2019-05-20	95.377 mi
Registration #15	2019-05-20	95.377 mi
Registration #16	2019-05-20	95.377 mi
Registration #17	2019-05-20	95.377 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1829 mm
Height	1700 mm
Length	4585 mm
Wheel base	2728 mm
Kerb weight	1530 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCV0048476