





report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Blue
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

Entry 1


Date 2021-07-01

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expire date	2022 02 17
MOT expiry date	2023-03-17
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	18
Total items failed	1

MOT #7	2022-03-11 11:31
MOT test number	952188256477
Result	✓ Passed
Next expiry date	2023-03-17
Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #6	2021-03-18 16:21
MOT test number	747743646718
Result	✓ Passed

MOT #5	2020-10-24 15:36
MOT test number	513317066877
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/12



Advice

Advice

LT64FND report date: 2024-03-29

MOT test number

Result

Advice
Offside Front wiper blade slightly deteriorated

Minor
Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice
Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice
Front Brake disc worn, but not excessively both (1.1.14 (a) (i))

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2019-10-29 15:13 **MOT** test number 859074064674 Result × Failed **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice **Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i)) Advice Offside Front wiper blade slightly deteriorated **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Fail Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))

MOT #2	2019-01-07 10:34
MOT test number	739859872123
Result	✓ Passed
Advice Nearside Front Nail in tyre	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 4/12



MOT #1 2017-12-19 10:11

MOT test number 846075745686

CarCheck.co.uk page 5/12



Tax & MOT check



MOT

Expired:
17 March 2023

Tax expired: 10 January 2023

Tax status

Days left

475 days too late

MOT expiry date

17 March 2023

Full MOT history

See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



LT64FND

report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



LT64FND

report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		NDAI

	More info	>
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-09-23
Last registration	2022-03-11
Complete history	See info



Registration #1	2014-09-23	12 mi
Registration #2	2017-12-19	32.226 mi
Registration #3	2019-01-07	44.153 mi
Registration #4	2019-10-29	52.101 mi
Registration #5	2019-10-29	52.101 mi
Registration #6		0.00 44
Registration #7		11.777 es
Registration #8		0.00 44
Registration #9		D.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	age 12/12

Number of axles 2

Engine number D4FDEZ258681