





report date: 2024-03-28

### General information

| Make                | HONDA                 |
|---------------------|-----------------------|
| Model               | CR-Z I-VTEC IMA SPORT |
| Colour              | Black                 |
| Year of manufacture | 2010                  |
| Top speed           | 124 mph               |
| 0 - 60 mph          | 10.0 seconds          |
| Gearbox             | 6 speed Manual        |

### Engine & fuel consumption

| Power                   | 113 BHP             |
|-------------------------|---------------------|
| Max. torque             | 145 Nm at 4.800 rpm |
| Engine capacity         | 1.497 cc            |
| Cylinders               | 4                   |
| Fuel type               | Hybrid / Electric   |
| Consumption city        | 46.3 mpg            |
| Consumption extra urban | 64.2 mpg            |
| Consumption combined    | 56.5 mpg            |
| CO2 emission            | 117 g/km            |
| CO2 label               | С                   |



CarCheck.co.uk page 1/13



## Internet history

| _ | _ | _ |    | _ | - |
|---|---|---|----|---|---|
| 드 | n | C | ľν | 7 | 1 |

| Life y 1      |             |
|---------------|-------------|
| Date          | 2021-11-18  |
| Pictures      | 0           |
| Listing price | View report |

source: cargurus.co.uk

CarCheck.co.uk page 2/13



## MOT history

| MOT expiry date    | 2024-07-27 |
|--------------------|------------|
| MOT pass rate      | 77 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 3          |
| Total advice items | 23         |
| Total items failed | 0          |

| MOT #13          | 2023-06-30 13:51 |
|------------------|------------------|
| MOT test number  | 874098072689     |
| Result           | <b>✓</b> Passed  |
| Next expiry date | 2024-07-27       |

| MOT #12         | 2022-07-21 16:20 |
|-----------------|------------------|
| MOT test number | 170964689552     |
| Result          | ✓ Passed         |

| MOT #11  |  | 2021-07-28 09:34 |
|----------|--|------------------|
| MOT test | number   | 715306385561     |
| Result   |  | <b>✓</b> Passed  |
| Advice   | Nearside rear tyre badly cracked and close to limit on edges |                  |
| Advice   | Rear discs and pads are very low                             |                  |
| Advice   | Offside rear tyre stepped and close to limit 195 55 16       |                  |

CarCheck.co.uk page 3/13



**Advice** 

Rear discs and pads are very low

EJ60TGN

report date: 2024-03-28

**MOT #10** 2021-07-22 07:49 346047868350 **MOT** test number Result × Failed **Advice** Front discs are worn **Advice** Offside rear tyre stepped and close to limit 195 55 16 Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) **MAJOR** Driver's door cannot be opened from outside the vehicle (6.2.3 (a)) **Advice** Nearside rear tyre badly cracked and close to limit on edges

MOT test number
905380589364

Result

Advice Front brake pads are very low

Advice Both rear tyres are stepped and cracked

Minor (b) (i))

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

| MOT #8         |   | 2020-07-20 09:04 |
|----------------|---|------------------|
| MOT test       | number  | 108535006402     |
| Result         |   | 🗙 Failed         |
| MAJOR          | Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))     |                  |
| Minor (b) (i)) | Nearside Registration plate lamp inoperative in the case of multiple lamps or light | t sources (4.7.1 |
| Advice         | Both rear tyres are stepped and cracked   |                  |
| MAJOR          | Offside Side repeater not working (4.4.1 (a) (ii))                                  |                  |
| Advice         | Front brake pads are very low   |                  |

CarCheck.co.uk page 4/13



MOT #7 2019-04-17 10:59

MOT test number 991361216697

**Result** ✓ Passed

**Advice** Offside Front tyre bold on inner edge

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2019-04-15 12:15

**MOT test number** 400903819938

**Result** X Failed

**MAJOR** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front tyre bold on inner edge

MOT #5 2018-01-08 15:40

MOT test number 333799735788

Result \( \sqrt{Passed} \)

**MOT #4** 2017-01-03 12:43

**MOT test number** 729191232817

Result \( \sqrt{Passed} \)

MOT #3 2016-01-05 10:56

**MOT test number** 292220514326

**Result** 
✓ Passed

MOT #2 2014-12-30 15:57

**MOT test number** 468594164355

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 5/13



**MOT #1** 2013-11-14 10:40

**MOT test number** 828348813304

**Result** ✓ Passed

CarCheck.co.uk page 6/13





## Tax & MOT check



| Tax status       | Valid until 1 December |
|------------------|------------------------|
| Days left        | 216                    |
| MOT expiry date  | 27 July 2024           |
| Full MOT history | See MOT history        |

### Tax calculation

| Vehicle class                           | 59             |
|---|----------------|
| Band                                    | С              |
| Single payment (12 months)              | £ 25,00,-      |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | £ 26,25,-      |

CarCheck.co.uk page 7/13



### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |  |
|----------|--|
| Date     |  |
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Type     |  |



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



| Owner  | hictor,  |
|--------|----------|
| UWNEI  | nisioiv  |
| OWINCE | THISCOLY |

| e when miscory   |             |   |
|--|-------------|---|
| For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it |             |   |
| **************************************   |             |   |
|  |             |   |
| ***************************************  |             |   |
| *********  |             |   |
|  |             |   |
| ***************************************  |             |   |
|  | More info > |   |
| Plate changes  |             |   |
| See in this check if this HONDA had different number plates.   |             |   |
| Number of plates   |             | , |
| Current registration   | UK UK       |   |
| Plate since  |             |   |
| Current registration   | UK NE       |   |
| Plate since  |             |   |
|  | More info > |   |

CarCheck.co.uk page 10/13



### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

Contact info

More info >

CarCheck.co.uk page 11/13



## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 15         |
| First mileage registration | 2010-12-10 |
| Last registration          | 2023-06-30 |
| Complete history           | See info   |



| Registration #1  | 2010-12-10 | 13 mi     |
|------------------|------------|-----------|
| Registration #2  | 2013-11-14 | 45.299 mi |
| Registration #3  | 2014-12-30 | 58.727 mi |
| Registration #4  | 2016-01-05 | 64.912 mi |
| Registration #5  | 2017-01-03 | 68.370 mi |
| Registration #6  | 2018-01-08 | 73.054 mi |
| Registration #7  | 2019-04-15 | 77.804 mi |
| Registration #8  | 2019-04-17 | 77.805 mi |
| Registration #9  |            | 11.777 es |
| Registration #10 |            | 71.777 es |
| Registration #11 |            | 9.70 es   |
| Registration #12 |            | 11.777 es |
| Registration #13 |            | 9.70 es   |
| Registration #14 |            | 11.777 es |
| Registration #15 |            | 9.777 es  |

More info >

CarCheck.co.uk page 12/13



## Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 93%             |
| Children       | 80%             |
| Pedestrian     | 71%             |
| Safety systems | 86%             |
| Overall rating | 85%             |
| Video          | see crash video |



# Dimensions & weight

| Width       | 2014 mm |
|-------------|---------|
| Height      | 1395 mm |
| Length      | 4080 mm |
| Wheel base  | 2425 mm |
| Kerb weight | 1198 kg |

## Additional information

| Fuel tank capacity | 40 I                  |
|--------------------|-----------------------|
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 3                     |
| Number of seats    | 4                     |
| Number of axles    | 2                     |
| Engine number      | LEA1 1016382          |

CarCheck.co.uk page 13/13