



SC08A0G

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO E (60BHP)
Colour	Black
Year of manufacture	2008
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





MOT history

MOT expiry date	2024-08-30
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	7
Total items failed	11

MOT #17	2023-08-31 12:45
MOT test number	593397500180
Result	✓ Passed
Next expiry date	2024-08-30

MOT #16	2022-02-01 08:58
MOT test number	553289326560
Result	✓ Passed

MOT #15	2021-01-07 10:49
MOT test number	486809956302
Result	✓ Passed

Advice Nearside Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #14	2020-12-04 12:49
MOT test number	190113566754

Result	✗ Failed
--------	----------

Advice Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Fail Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Front Suspension arm corroded and seriously weakened holed (5.3.3 (b) (i))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #13** 2019-06-03 15:09**MOT test number** 972402857354**Result** ✓ Passed**MOT #12** 2019-06-03 09:58**MOT test number** 252645682824**Result** ✗ Failed**Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #11** 2018-06-07 09:02**MOT test number** 539629392538**Result** ✓ Passed**Advice** Rear silencer has slight corrosion**MOT #10** 2018-06-07 09:02**MOT test number** 876053432017**Result** ✗ Failed**Advice** Rear silencer has slight corrosion**Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #9** 2017-05-26 15:01**MOT test number** 512119090945**Result** ✓ Passed

**MOT #8** 2017-05-26 10:38**MOT test number** 138670086849**Result** ✗ Failed**Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Coil spring not correctly located (2.4.C.2)**Fail** Offside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #7** 2016-05-05 09:29**MOT test number** 354847991181**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-05-05 09:29**MOT test number** 753624784725**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-05-29 14:06**MOT test number** 717769945173**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #4** 2014-05-31 09:48**MOT test number** 539211854187**Result** ✓ Passed



MOT #3	2013-05-25 10:54
MOT test number	586105243187
Result	✓ Passed
MOT #2	2012-05-30 11:06
MOT test number	675831152147
Result	✓ Passed
MOT #1	2011-05-20 17:28
MOT test number	805110541193
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-05-30
Last registration	2023-08-31
Complete history	See info



Registration #1	2008-05-30	11 mi
Registration #2	2011-05-20	33.813 mi
Registration #3	2012-05-30	45.864 mi
Registration #4	2013-05-25	56.566 mi
Registration #5	2014-05-31	63.021 mi
Registration #6	2015-05-29	68.444 mi
Registration #7	2016-05-05	77.768 mi
Registration #8	2016-05-05	77.768 mi
Registration #9	2017-05-26	84.547 mi
Registration #10	2018-05-29	91.377 mi
Registration #11	2019-05-29	98.207 mi
Registration #12	2020-05-29	105.037 mi
Registration #13	2021-05-29	111.867 mi
Registration #14	2022-05-29	118.697 mi
Registration #15	2023-05-29	125.527 mi
Registration #16	2024-05-29	132.357 mi
Registration #17	2025-05-29	139.187 mi
Registration #18	2026-05-29	146.017 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1092 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BBM184158