





report date: 2024-03-29

General information

Make	MAZDA
Model	CX-5 SPORT NAV PLUS
Colour	Silver
Year of manufacture	-
Top speed	119 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	213 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	36.7 mpg



CarCheck.co.uk page 1/10



report date: 2024-03-29

Internet history

Entry 1


Date 2022-06-22

Pictures 32

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-29

MOT history

MOT #4		2023-04-17 11:15
MOT test	number	851701161277
Result		✓ Passed
Next expi	ry date	2024-04-19
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	())

MOT #3	2022-04-20 10:14
MOT test number	325612947856
Result	✓ Passed
MOT #2	2022-02-21 16:24
MOT test number	832340911441

MOT test	number	832340911441
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/10



report date: 2024-03-29

MOT #1 2022-01-26 17:06 **MOT test number** 713908187558 Result × Failed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

CarCheck.co.uk page 4/10



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



SV68HSO report date: 2024-03-29

Owner history

•		
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		А

	More info	>
Plate changes		
See in this check if this MAZDA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 7/10



SV68HSO report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-12-04
Last registration	2023-04-17
Complete history	See info



Registration #1	2018-12-04	6 mi
Registration #2	2022-01-26	5.060 mi
Registration #3	2022-02-21	5.063 mi
Registration #4		71.777 66
Registration #5		11.777 es
Registration #6		n.m.

More info >

CarCheck.co.uk page 9/10



SV68HSO report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	95%
Children	80%
Pedestrian	78%
Safety systems	59%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1680 mm
Length	4550 mm
Wheel base	2700 mm
Kerb weight	1480 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	56 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	PE 31270881

CarCheck.co.uk page 10/10