





report date: 2024-03-29

General information

Make	MINI
Model	MINI (R57) COOPER D
Colour	White
Year of manufacture	2011
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	140 g/km
CO2 label	E



CarCheck.co.uk page 1/13



Internet history

Entry 2

Date 2021-10-03

Pictures 50

Listing price View report









source: cargurus.co.uk

Entry 1

Date	2021-07-08
Pictures	50

Listing price View report









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-09-20
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	29
Total items failed	4

MOT #13	2023-09-21 08:15
MOT test number	679541109518
Result	✓ Passed
Next expiry date	2024-09-20

MOT #12	2022-09-07 16:22
MOT test number	846609498743
Result	√ Passed

MOT #11	2022-09-06 09:15
MOT test number	261232451080
Result	× Failed
Fail Nearside Front Tyre has ply or cords exposed 195/55/16 (5.2.3 (d) (ii))	
Fail Bonnet cannot be secured in the closed position (3.1 (b) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))

MOT #10	2021-08-31 09:58
MOT test number	793542582964
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #9 2020-09-08 15:53 452323449736 **MOT test number** Result ✓ Passed **Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Offside Windscreen wiper blade defective (3.4 (b) (i)) Minor Minor Nearside Windscreen wiper blade defective (3.4 (b) (i)) **Advice** All road wheels slightly protrude wheel arches **Advice** Items removed from driver's view prior to test Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #8		2019-09-03 16:48
MOT test	number	966662683031
Result		✓ Passed
Advice	Wheel/tyre protruding beyond wheel arch Front & rear wheels'	
Advice	Front Brake disc worn, but not excessively ns/os (1.1.14 (a) (i))	
Advice	Items removed from driver's view prior to test	
Advice	Rear Brake disc worn, but not excessively ns/os (1.1.14 (a) (i))	

MOT #7		2018-04-11 15:32
MOT test	number	261774475610
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear tyre perished and close to limit	
Advice	Nearside Rear tyre perished and close to the limit	
Advice	Offside Front tyre perished and close to limit.	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #6 2018-04-11 15:32 **MOT** test number 357437652356 Result × Failed **Advice** Offside Front tyre perished and close to limit. Advice Offside Rear tyre perished and close to limit Advice Rear Brake pad(s) wearing thin (3.5.1g) Advice Nearside Rear tyre perished and close to the limit Pass with rectification Fuel system component leaking (7.2.3)

MOT test number

Result

Advice Items removed from driver's view prior to test

Advice OSF and both rear tyres perished and sidewalls cracked.

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT test number

Result

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice

OSF and both rear tyres perished and sidewalls cracked.

Advice

Items removed from driver's view prior to test

Pass with rectification

Offside Registration plate lamp not working (1.1.C.1d)

 MOT #3
 2016-04-14 13:32

 MOT test number
 565925834458

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



MOT #2		2015-04-10 17:18
MOT test number		769890705126
Result		✓ Passed
Notice Engine	covers fitted obscuring some components in the engine bay	
Notice Under-	trays fitted obscuring some underside components	

MOT #1		2014-06-05 09:29
MOT test	number	207456754464
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Engine covers fitted obscuring some components in the engine bay	

CarCheck.co.uk page 6/13



Tax & MOT check



✓ MOT

Tax expired: 1 April 2024 Expires: 20 September 2024

Tax status	Expired at 1 April 2024
Days left	29 days too late
MOT expiry date	20 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report h		e?
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-30
Last registration	2023-09-21
Complete history	See info



Registration #1	2011-09-30	11 mi
Registration #2	2014-06-05	30.024 mi
Registration #3	2015-04-10	30.927 mi
Registration #4	2016-04-14	41.689 mi
Registration #5	2017-04-20	53.824 mi
Registration #6	2017-04-20	53.824 mi
Registration #7	2018-04-11	66.573 mi
Registration #8	2018-04-11	66.573 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		D.777 es
Registration #15		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1225 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	40 I	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	4 page 13,	13

Number of axles 2

Engine number 72017895