





report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 LX
Colour	Silver
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	111 Nm at 2.600 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-21

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT #21 2021-11-23 16:42

MOT test number 855617858001

Result ✓ Passed

Next expiry date 2022-11-22

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #20 2021-11-11 11:16

MOT test number 170409640414

Result X Failed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Side repeater missing (4.4.1 (a) (ii))

Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Oil leaking excessively from engine (8.4.1 (a) (i))

Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #19 2020-11-14 09:59

MOT test number 662821789072

Result ✓ Passed

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #18 2020-11-13 13:08

MOT test number 430425241227

Result X Failed

Advice Offside Side repeater slightly discoloured (4.4.3 (a))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #17 2019-12-27 16:56

MOT test number 323072890068

Result \(\sqrt{Passed} \)

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16 2019-01-26 12:11

MOT test number 401068778133

Result

Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #15 2019-01-22 16:18 **MOT** test number 529447769667 Result × Failed **Advice** Both front discs rusted up Fail Front Service brake imbalanced across an axle (1.2.1 (b) (i)) Fail Offside Front Suspension rod ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Nearside Front Suspension rod ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) Fail (ii)) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT test number

279556299855

Result

Advice dirt (2.4.G.2)

Advice Rear Exhaust has a minor leak of exhaust gases box (7.1.2)

Advice (2.4.G.2)

Advice Rear Exhaust has a minor leak of exhaust gases box (7.1.2)

MOT #13 2016-12-09 12:39
MOT test number 489781674598
Result ✓ Passed

MOT #12

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



Result

GU53MVT

report date: 2024-03-28

✓ Passed

MOT #11		2014-09-10 16:16
MOT test number		309603454293
Result		✓ Passed
MOT #10		2013-08-29 17:27
MOT test number		186931543275
Result		✓ Passed
MOT #9		2012-09-11 15:53
MOT test number		217265852295
Result		✓ Passed
MOT #8		2011-09-05 14:59
MOT test number		577108041263
Result		✓ Passed
MOT #7		2010-09-04 15:27
MOT test number		891727640204
Result		√ Passed
MOT #6		2010-09-04 15:27
MOT test number		851117540213
Result		× Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)	
	· , ,	
MOT #5		2009-09-04 17:41
MOT test number		281557249263

CarCheck.co.uk page 6/13



report date: 2024-03-28

MOT #4	2008-08-13 10:10
MOT test number	783886428253
Result	✓ Passed
MOT #3	2007-08-09 15:05
MOT test number	783701427230
Result	✓ Passed
MOT #2	2007-08-08 12:04
MOT test number	642040027263
Result	X Failed
Fail Offside Front constant velocity joint gaiter split (2.5.C.1a)	

MOT #1		2006-08-25 15:54
MOT test	number	271277036223
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



GU53MVT report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

GU53MVT

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this PEUGEOT had different number plates.

CarCheck.co.uk page 10/13



GU53MVT report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 11/13





report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-09-06
Last registration	2021-11-23
Complete history	See info



Registration #1	2003-09-06	18 mi
Registration #2	2006-08-25	10.382 mi
Registration #3	2007-08-08	15.332 mi
Registration #4	2007-08-09	15.332 mi
Registration #5	2008-08-13	18.856 mi
Registration #6	2009-09-04	21.628 mi
Registration #7	2010-09-04	24.260 mi
Registration #8	2011-09-05	27.232 mi
Registration #9	2012-09-11	29.442 mi
Registration #10	2013-08-29	31.478 mi
Registration #11	2014-09-10	34.091 mi
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.777 es
Registration #16		11.777 es
Registration #17		0.07 m
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		71.777 66

More info >

CarCheck.co.uk page 12/13



GU53MVT report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	950 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	FSI44493145

CarCheck.co.uk page 13/13