






report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 SWB P/V 130TDI
Colour	Black
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	130 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	22.2 mpg
Consumption extra urban	35.8 mpg
Consumption combined	29.4 mpg



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-08-27

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-13
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	29
Total items failed	9

MOT #15		2024-01-08 14:50
MOT test	number	116519202427
Result		✓ Passed
Next expi	ry date	2025-01-13
Advice	Exhaust outer skin corroded	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice (i))	Suspension arm pin or bush worn but not resulting in excessive movemen	nt both fronts (5.3.4 (a)

MOT #14	2023-01-05 14:40
MOT test i	number 303130728489
Result	✓ Passed
Advice	Fluid leak, but not excessive (8.4.1 (a) (i))
Advice	Exhaust corroded
Advice	Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))

MOT #13		2022-01-14 14:17
MOT test	number	192796632995
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 235/50r18 (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #12 2022-01-14 11:49

MOT test number 353850853150

Result X Failed

Fail Offside Front Service brake excessively binding (1.2.1 (f))

Fail Emissions not tested Turbo pipe not attached under bonnet. (8.2.2.2 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Emission control equipment obviously defective Turbo pipe disconnected under bonnet. (8.2.2.1 (a))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 235/50r18 (5.2.3 (e))

MOT #11 2021-03-01 15:27

MOT test number 790088870274

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10 2021-02-27 11:27

MOT test number 576324565678

Result × Failed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9 2020-03-02 14:09

MOT test number 581233200172

Result ✓ Passed

CarCheck.co.uk page 4/12



Result

VO58JVR report date: 2024-03-28

★ Failed

MOT #8 2019-06-19 10:45

MOT test number 588042861327

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #7 2019-06-14 10:27

MOT test number 566241821281

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #6 2017-09-07 11:18

MOT test number 835204455631

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 5/12



MOT test number

Segretary

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Eml on

Advice Oil leak

MOT #4

MOT test number

619452845057

Result

Notice EML ON

Advice Inner Front Brake pad(s) wearing thin (3.5.1g)

Notice Back box deteriorated

MOT #3

MOT test number

546954363227

Result

Notice EML ON

Notice Back box deteriorated

MOT #2

MOT test number

458564062228

Result

→ Passed

 MOT #1
 2011-09-01 12:56

 MOT test number
 168514541252

 Result
 ✓ Passed

CarCheck.co.uk page 6/12



Tax & MOT check



Tax status

Days left

MOT expiry date

13 January 2025

Full MOT history

See MOT history

CarCheck.co.uk page 7/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.


Damage 1

Date	
Category	
Туре	
Damage 2	

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Mumber of plates	,
Current registration	UK UK
Plate since	
Current registration	UK ZIN
Plate since	
	More info

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-01
Last registration	2024-01-08
Complete history	See info



Registration #1	2008-09-01	6 mi
Registration #2	2011-09-01	18.542 mi
Registration #3	2012-09-20	24.613 mi
Registration #4	2013-09-21	29.081 mi
Registration #5	2015-02-11	39.096 mi
Registration #6	2016-09-01	53.488 mi
Registration #7	2017-09-07	60.409 mi
Registration #8	2019-06-14	68.169 mi
Registration #9	2019-06-19	68.171 mi
Registration #10		11.777 es
		11.777 es
Registration #10		11.777 ea 11.777 ea 11.777 ea
Registration #10 Registration #11		11.777 ea 11.777 ea 11.777 ea
Registration #10 Registration #11 Registration #12		11.77 es 11.77 es 11.77 es
Registration #10 Registration #11 Registration #12 Registration #13		11.77 ea 21.77 ea 21.77 ea 21.77 ea 21.77 ea
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14		11.777 ea 21.777 ea 21.777 ea 21.777 ea 21.777 ea

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1904 mm
Height	1969 mm
Length	4890 mm
Kerb weight	1872 kg

Additional information

_	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2

CarCheck.co.uk page 12/12

Engine number

BNZ 091171