





report date: 2024-03-29

## General information

Make	MAZDA
Model	cx-3 D SE NAV
Colour	White
Year of manufacture	2017
Top speed	110 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	104 BHP
Max. torque	270 Nm at 1.600 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/11



## Internet history

## Entry 1

Date 2021-06-15

Pictures 68

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



**MOT** history

MOT #2

MOT expiry date	2024-06-22
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #5	2023-06-23 13:08
MOT test number	342189327841
Result	✓ Passed
Next expiry date	2024-06-22

MOT #4	2022-06-20 13:08
MOT test number	802653282219
Result	✓ Passed

MO1 #3		2021-04-27 11.39
<b>MOT</b> test	number	456203321312
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge worn on outside (5.2.3	(e))

Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Offside Windscreen damaged but not adversely affecting driver's view has a stone chip (3.2 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on inner and outer edges (5.2.3 (e))

CarCheck.co.uk page 3/11



**MOT #2** 2021-04-27 07:58

MOT test number 645605710662

Result X Failed

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative light is on (5.2.3 (h))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on inner and outer edges (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge worn on outside (5.2.3 (e))

**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2020-04-29 14:41

**MOT test number** 278094409283

**Result** ✓ Passed

**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	22 June 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 7/11



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
HARMAN CO. C.	
********	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	NK.
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info


More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-03-29
Last registration	2023-06-23
Complete history	See info



Registration #1	2017-03-29	20 mi
Registration #2	2020-04-29	22.691 mi
Registration #3	2021-04-27	28.673 mi
Registration #4	2021-04-27	28.673 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		D.777 es

More info >

CarCheck.co.uk page 10/11



## Safety ratings

NCAP rating	****
Adult	85%
Children	79%
Pedestrian	84%
Safety systems	64%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1535 mm
Length	4275 mm
Wheel base	2570 mm
Kerb weight	1200 kg
Max. allowed weight	1735 kg

## Additional information

Fuel tank capacity	48
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	S5 30 381959

CarCheck.co.uk page 11/11