



PEUGEOT



KMI3HFF

report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | PEUGEOT |
| Model | 107 ACTIVE |
| Colour | Black |
| Year of manufacture | 2013 |
| Top speed | 100 mph |
| 0 - 60 mph | 14.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|--------------------|
| Power | 68 BHP |
| Max. torque | 93 Nm at 3.600 rpm |
| Engine capacity | 998 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 55.4 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 65.7 mpg |
| CO2 emission | 99 g/km |
| CO2 label | A |






Internet history

Entry 2



| | |
|---------------|-----------------------------|
| Date | 2021-09-10 |
| Pictures | 21 |
| Listing price | View report |



source: yesauto.com

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-08 |
| Pictures | 21 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-29 |
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 13 |
| Total items failed | 4 |

| | |
|------------------|--|
| MOT #10 | 2023-06-22 11:09 |
| MOT test number | 566859644218 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-29 |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|------------------|
| MOT #9 | 2022-06-22 13:14 |
| MOT test number | 442324249989 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #8 | 2021-06-30 07:09 |
| MOT test number | 521993772357 |
| Result | ✓ Passed |

**MOT #7** 2020-10-20 14:43**MOT test number** 319281044073**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Nail in tyre**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2020-10-19 13:19**MOT test number** 421353154114**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Nail in tyre**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #5** 2019-04-11 11:42**MOT test number** 929711499957**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing both cracking/perishing/slightly misshapen (5.2.3 (d) (ii))

**MOT #4** 2019-04-11 11:42**MOT test number** 828768897177**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing both cracking/perishing/slightly misshapen (5.2.3 (d) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #3** 2018-03-26 09:50**MOT test number** 749206399056**Result** ✓ Passed**MOT #2** 2017-03-27 10:36**MOT test number** 657452114434**Result** ✓ Passed**MOT #1** 2016-04-13 13:52**MOT test number** 449619951983**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
29 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 126 |
| MOT expiry date | 29 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 48 |
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2013-04-24 |
| Last registration | 2023-06-22 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-04-24 | 24 mi |
| Registration #2 | 2016-04-13 | 24.139 mi |
| Registration #3 | 2017-03-27 | 31.064 mi |
| Registration #4 | 2018-03-26 | 35.912 mi |
| Registration #5 | 2019-04-11 | 42.062 mi |
| Registration #6 | 2019-04-11 | 42.062 mi |
| Registration #7 | 2020-10-19 | 50.765 mi |
| Registration #8 | 2021-06-22 | 55.277 mi |
| Registration #9 | 2021-06-22 | 55.277 mi |
| Registration #10 | 2021-06-22 | 55.277 mi |
| Registration #11 | 2021-06-22 | 55.277 mi |
| Registration #12 | 2021-06-22 | 55.277 mi |
| Registration #13 | 2023-06-22 | 55.277 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 68% |
| Children | 73% |
| Pedestrian | 53% |
| Safety systems | 71% |
| Overall rating | 66% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1855 mm |
| Height | 1470 mm |
| Length | 3430 mm |
| Wheel base | 2340 mm |
| Kerb weight | 900 kg |
| Max. allowed weight | 1180 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 35 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 4 |

Engine number

7381315